



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	White
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-16
Pictures	30
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-18
Pictures	30
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-06-16
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	26
Total items failed	3

MOT #12 2023-06-09 08:12**MOT test number** 324779971850**Result** Passed**Next expiry date** 2024-06-16

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Slight sidewall damage nearside front tyre.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside and nearside front brake discs corroded, inner surface.
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2022-06-17 08:51**MOT test number** 648234346374**Result** Passed

- Advice** Offside and nearside front brake discs corroded, inner surface.
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2021-06-09 09:54**MOT test number** 432645325606**Result** Passed

**MOT #9** 2021-06-07 15:12**MOT test number** 100208209789**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Headlamp aim projected beam image is obviously incorrect Both Sides. (4.1.2 (c))**Advice** Front Tyre worn close to legal limit/worn on edge Both Sides. (5.2.3 (e))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn & Cuts. (5.2.3 (e))**MOT #8** 2020-06-02 11:57**MOT test number** 550717777916**Result** ✓ Passed**MOT #7** 2019-05-20 08:43**MOT test number** 496015107748**Result** ✓ Passed**MOT #6** 2018-04-27 14:07**MOT test number** 577123412543**Result** ✓ Passed

**MOT #5** 2017-05-02 09:49**MOT test number** 132100736032**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Both rear tyres bald on inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-04-29 13:22**MOT test number** 501538125770**Result** ✓ Passed**MOT #3** 2015-05-26 12:20**MOT test number** 838466245132**Result** ✓ Passed**Notice** Wipers smeary**Notice** Passengers front tyre wearing inner edge**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Drivers front tyre wearing inner edge



MOT #2	2014-05-14 15:11
MOT test number	216004034165
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Notice	Emissions to clean to test

MOT #1	2013-05-17 14:16
MOT test number	439097433110
Result	✓ Passed
Notice	Rear pads 60-70% worn
Notice	Both front tyres bald inner edges
Notice	Both front tyres on 1.6mm legal limit



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	16 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-31
Last registration	2023-06-09
Complete history	See info



Registration #1	2011-05-31	18 mi
Registration #2	2013-05-17	29.246 mi
Registration #3	2014-05-14	40.836 mi
Registration #4	2015-05-26	53.576 mi
Registration #5	2016-04-29	63.291 mi
Registration #6	2017-05-02	75.332 mi
Registration #7	2018-04-27	87.303 mi
Registration #8	2019-05-20	98.510 mi
Registration #9	2020-05-20	109.717 mi
Registration #10	2021-05-20	120.924 mi
Registration #11	2022-05-20	132.131 mi
Registration #12	2023-05-20	143.338 mi
Registration #13	2024-05-20	154.545 mi
Registration #14	2025-05-20	165.752 mi
Registration #15	2026-05-20	176.959 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102