



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Blue
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-07-23
Pictures	16
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-10
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-02
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	8

MOT #13	2024-01-03 14:30
MOT test number	332269292288
Result	✓ Passed
Next expiry date	2025-01-02
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2024-01-03 14:30
MOT test number	734132553120
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2023-01-03 11:50
MOT test number	552478585214
Result	✓ Passed

MOT #10	2021-12-21 14:09
MOT test number	441701804872
Result	✓ Passed

**MOT #9**

2021-07-21 10:40

MOT test number

690024180813

Result

✓ Passed

Advice Offside Rear light unit cracked**Advice** Offside Front fog light unit insecure**MOT #8**

2021-07-19 16:15

MOT test number

346229532150

Result

✗ Failed

Advice Offside Rear light unit cracked**Fail** Offside Front Outline marker lamp does not illuminate simultaneously with the position lamps (4.2.2 (a))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front fog light unit insecure**Fail** Windscreen washer not working (3.5 (a))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7**

2020-07-09 08:18

MOT test number

705214288571

Result

✓ Passed

Advice Engine cover /under tray fitted obscuring testable items**Advice** Offside Rear Inner edge has uneven wear on tyre

**MOT #6** 2019-04-24 11:23**MOT test number** 910889850916**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-05-14 08:41**MOT test number** 989782889842**Result** ✓ Passed**MOT #4** 2017-04-10 13:15**MOT test number** 319785194663**Result** ✓ Passed**MOT #3** 2016-04-04 14:11**MOT test number** 826468404561**Result** ✓ Passed**MOT #2** 2015-04-13 14:53**MOT test number** 198123905161**Result** ✓ Passed**MOT #1** 2015-04-13 14:53**MOT test number** 269473505472**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 January 2025

Tax status	Valid until 1 December
Days left	217
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 VK12XGC
Plate since	2019-09-28
Current registration	 VK12XGC
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-16
Last registration	2024-01-03
Complete history	See info



Registration #1	2012-04-16	12 mi
Registration #2	2015-04-13	53.953 mi
Registration #3	2016-04-04	57.233 mi
Registration #4	2017-04-10	63.293 mi
Registration #5	2018-05-14	68.875 mi
Registration #6	2019-04-24	73.014 mi
Registration #7	2020-07-09	75.575 mi
Registration #8	2020-05-20	75.575 mi
Registration #9	2020-05-20	75.575 mi
Registration #10	2020-05-20	75.575 mi
Registration #11	2020-05-20	75.575 mi
Registration #12	2020-05-20	75.575 mi
Registration #13	2020-05-20	75.575 mi
Registration #14	2020-05-20	75.575 mi
Registration #15	2020-05-20	75.575 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1133407