





report date: 2024-03-29

General information

Make	MINI
Model	COOPER SD
Colour	White
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 2.700 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-09

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	29
Total items failed	4

MOT #14	2024-04-09 10:54
MOT test number	477215517052
Result	✓ Passed
Next expiry date	2025-04-17

MOT #13		2023-04-18 12:17
MOT test	number	894436745453
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice (5.3.4 (a) (Front Lower Suspension arm pin or bush worn but not resulting in excessive n	novement Both sides

MOT #12	2022-04-09 07:18
MOT test number	760006420218
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	

CarCheck.co.uk page 3/13



Advice

HG61YLA report date: 2024-03-29

MOT #11

MOT test number

Result

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number
923687837085

Result
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification obstruction (3.1 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9		2020-02-11 15:24
MOT test	number	387565321141
Result		✓ Passed
Advice	Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Items removed from driver's view prior to test	

CarCheck.co.uk page 4/13



MOT #8

HG61YLA

report date: 2024-03-29

2020-02-11 09:39

MOT test number

Result

Advice Items removed from driver's view prior to test

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cut on the outer sidewall (5.2.3 (d) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT test number

Result

Advice

Nearside Front Seat belt slightly damaged slightly freying edge (7.1.2 (b) (i))

Advice

Mud and snow tyres fitted diagonally (not on same axle)

Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT test number

Result

Nearside Headlamp aim too low (4.1.2 (a))

Advice

Nearside Front Seat belt slightly damaged slightly freying edge (7.1.2 (b) (i))

Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Mud and snow tyres fitted diagonally (not on same axle)

 MOT #5
 2017-11-29 09:45

 MOT test number
 287726104166

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #4 2016-11-11 11:32

MOT test number 830803687069

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2016-11-11 11:32

MOT test number 642079606448

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2015-08-17 13:53

MOT test number 167111364275

Result ✓ Passed

MOT #1 2014-08-07 11:48

MOT test number 467539114275

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



HG61YLA

report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



HG61YLA

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-29
Last registration	2024-04-09
Complete history	See info



Registration #1	2011-09-29	14 mi
Registration #2	2014-08-07	7.716 mi
Registration #3	2015-08-17	9.927 mi
Registration #4	2016-11-11	13.809 mi
Registration #5	2016-11-11	13.809 mi
Registration #6	2017-11-29	18.258 mi
Registration #7	2018-12-03	22.185 mi
Registration #8	2018-12-03	22.185 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		H 777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/

Engine number

71667897