





# General informationMakeVAUXHALLModelVIVARO L2H1 2900 COMBI CDTI BITURBO S/SColourSilverYear of manufacture2017Gearbox6 speed Manual

# Engine & fuel consumption

Power	123 BHP	0 < 101 A
Max. torque	320 Nm at 1.500 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.598 cc	121 - 140 E
Cylinders	4	141 - 165 F LABEL F
Fuel type	Diesel	166 - 185 H
Consumption city	44.1 mpg	186 - 225 J
Consumption extra urban	53.3 mpg	225+ L M
Consumption combined	49.6 mpg	
CO2 emission	145 g/km	
CO2 label	F	





## Internet history

Entry 1		
Date	2021-07-13	
Pictures	7	

Listing price

View report

Rac

All cars come with at least 3 months RAC Warranty & 12 months complimentary RAC Breakdown Cover\*







source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-08
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	11
Total items failed	0

МОТ #6	2024-04-09 11:11
MOT test number	567027040436
Result	✓ Passed
Next expiry date	2025-04-08

MOT #5	2023-07-18 13:19
MOT test number	561598918798
Result	✓ Passed
Advice Handbrake cables corroded	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)	))
Advice Front Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))





MOT #4		2022-07-12 15:43
MOT test	number	366157455491
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear parking brake cables corroded	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2021-07-29 08:46
MOT test number	766132832840
Result	✓ Passed

MOT #2	2020-09-14 14:40
MOT test number	472554032259
Result	✓ Passed
Minor Nearside Registration plate lamp inoperative in the case of multiple land (b) (i))	mps or light sources (4.7.1
Advice Nearside Rear Nail in tyre	

MOT #1	2019-10-10 12:28
MOT test number	666246717030
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ МОТ	
Tax due: 1 March 2025	Expires: 8 April 2025	
Tax status	Valid until 1 March	
Days left	305	
MOT expiry date	8 April 2025	
Full MOT history	See MOT history	

## Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-18
Last registration	2024-04-09
Complete history	See info



Registration #1	2017-09-18	25 mi
Registration #2	2019-10-10	17.869 mi
Registration #3	2020-09-14	41.066 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 esi

More info  $\rightarrow$ 





# Safety ratings

NCAP rating	****	and a second
Adult	52%	EURO
Children	91%	
Pedestrian	53%	-
Safety systems	57%	
Overall rating	61%	
Video	see crash video	



Dimensions & weight	
Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1842 kg
Max. allowed weight	3020 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	R9M MH - C199198LQI