



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-21
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	11

MOT #13 2023-09-14 12:20

MOT test number 530608382005

Result ✓ Passed

Next expiry date 2024-09-21

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

MOT #12 2022-09-20 13:01

MOT test number 236585267666

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2021-09-22 16:17

MOT test number 122693238293

Result ✓ Passed

**MOT #10** 2021-07-02 13:48**MOT test number** 366226789913**Result** ✗ Failed

- Fail** Front Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #9 2020-07-10 12:05**MOT test number** 240991848887**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2020-07-10 11:58**MOT test number** 246666064282**Result** ✗ Failed

- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2020-07-10 08:18**MOT test number** 376269106909**Result** ✗ Failed

- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Central heatshield loose

MOT #6 2019-01-09 17:31**MOT test number** 282859479510**Result** ✓ Passed**MOT #5** 2019-01-09 17:31**MOT test number** 498979218199**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #4 2016-09-12 13:31**MOT test number** 564115956220**Result** ✓ Passed

- Advice** Both rear tyres cracking slightly on outer side wall



MOT #3	2015-04-23 15:01
MOT test number	395933915106
Result	✓ Passed

MOT #2	2014-04-15 09:40
MOT test number	836295404122
Result	✓ Passed
<div>Advice</div> Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2013-04-19 11:02
MOT test number	726409503174
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-30
Last registration	2023-09-14
Complete history	See info



Registration #1	2010-04-30	8 mi
Registration #2	2013-04-19	24.194 mi
Registration #3	2014-04-15	32.703 mi
Registration #4	2015-04-23	40.111 mi
Registration #5	2016-09-12	40.609 mi
Registration #6	2019-01-09	41.654 mi
Registration #7	2019-01-09	41.654 mi
Registration #8	2020-07-10	44.399 mi
Registration #9	2022-05-20	55.377 mi
Registration #10	2022-05-20	55.377 mi
Registration #11	2022-05-20	55.377 mi
Registration #12	2022-05-20	55.377 mi
Registration #13	2022-05-20	55.377 mi
Registration #14	2022-05-20	55.377 mi
Registration #15	2022-05-20	55.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AY19587