





report date: 2024-03-28

# General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Blue
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



# Internet history

_	_	_		_	-
드	n	C	ľν	7	1

ciitiy 1	
Date	2021-08-30
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #11	2024-04-03 14:31
MOT test number	635552666859
Result	✓ Passed
Next expiry date	2025-04-04

MOT #10	2023-04-05 10:17
MOT test number	288174757100
Result	✓ Passed

MOT #9	2023-04-05 07:36
MOT test number	799719775869
Result	<b>×</b> Failed
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  Fail Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #8	2022-03-18 14:28
MOT test number	655110169026
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT #7 2022-03-18 11:00

**MOT test number** 383740877382

**Result** X Failed

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #6 2021-03-24 15:23

**MOT test number** 849957168779

**Result** ✓ Passed

MOT #5 2021-03-24 10:18

**MOT test number** 418099490732

**Result** X Failed

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**Fail** Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #4 2020-03-06 10:49

MOT test number 596464891967

Result 

Passed

**Advice** Windscreen washers poor

MOT #3 2019-03-08 11:39

MOT test number 927080889870

Result 

Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Child seat fitted not allowing full inspection of an adult belt

Advice Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2017-03-31 10:23
MOT test number	621799735959
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	AK AK
Plate since	
Current registration	NIK NIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-31
Last registration	2024-04-03
Complete history	See info



Registration #1	2014-03-31	29 mi
Registration #2	2017-03-31	42.898 mi
Registration #3	2018-03-28	56.828 mi
Registration #4	2019-03-08	67.136 mi
Registration #5	2020-03-06	76.876 mi
Registration #6	2021-03-24	83.104 mi
Registration #7	2021-03-24	83.104 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

# Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

**Engine number** D4FDEU412572