




General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	White
Year of manufacture	2011
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-17
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-08-18
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	25
Total items failed	10

MOT #12	2021-08-19 10:55
MOT test number	542368745093
Result	✓ Passed
Next expiry date	2022-08-18

MOT #11	2021-08-16 13:00
MOT test number	423381100224
Result	✗ Failed
Fail	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Front Suspension component mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
Fail	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #10	2019-11-25 14:39
MOT test number	113632805153
Result	✓ Passed

**MOT #9** 2018-11-19 14:35**MOT test number** 203199368687**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** O/s/f cv joint noisy**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-11-19 10:00**MOT test number** 478717361534**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate incorrect (0.1 (c))**Advice** O/s/f cv joint noisy**MOT #7** 2017-11-21 10:09**MOT test number** 381095666561**Result** ✓ Passed**MOT #6** 2016-11-22 16:14**MOT test number** 331499822359**Result** ✓ Passed



MOT #5 2016-06-22 09:44

MOT test number 877772776844

Result ✓ Passed

- Advice** Rear Wiper blade torn
- Advice** Offside Front Tyre worn on inner and outer edges
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit Tyre on 2mm on lowest point (4.1.E.1)
- Advice** Nearside Front Tyre worn on inner and outer edges
- Advice** Oil leak From engine
- Advice** Nearside Rear Tyre worn close to the legal limit Tyre on 2mm on lowest point (4.1.E.1)

MOT #4 2016-06-22 09:44

MOT test number 366354279210

Result ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit Tyre on 2mm on lowest point (4.1.E.1)
- Advice** Rear Wiper blade torn
- Advice** Offside Front Tyre worn on inner and outer edges
- Advice** Oil leak From engine
- Advice** Nearside Rear Tyre worn close to the legal limit Tyre on 2mm on lowest point (4.1.E.1)
- Advice** Nearside Front Tyre worn on inner and outer edges
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #3** 2015-04-18 10:52**MOT test number** 156218605152**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #2** 2014-04-03 17:51**MOT test number** 156743994022**Result** ✓ Passed**MOT #1** 2014-04-02 18:04**MOT test number** 678202594029**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Front Headlamp aim too far to the right (1.8)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	SD11TSZ
Plate since	2024-03-29
Current registration	SD11TSZ
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-31
Last registration	2021-08-19
Complete history	See info



Registration #1	2011-03-31	15 mi
Registration #2	2014-04-02	19.709 mi
Registration #3	2014-04-03	19.709 mi
Registration #4	2015-04-18	44.342 mi
Registration #5	2016-06-22	68.193 mi
Registration #6	2016-06-22	68.193 mi
Registration #7	2016-11-22	72.116 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2021-08-19	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Kerb weight	1865 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10282742