





report date: 2024-03-28

# General information

Make	NISSAN
Model	ELGRAND
Colour	White
Year of manufacture	2004
Gearbox	-

# Engine & fuel consumption

Engine capacity	3.490 cc
Fuel type	Petrol



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-09-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Date	2021-06-27
------	------------


Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



**MOT** history

MOT expiry date	2024-05-24
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	16
Total items failed	0

MOT #10	2023-05-25 16:08
MOT test number	777741671531
Result	<b>✓</b> Passed
Next expiry date	2024-05-24

MOT #9	2023-05-24 16:07
MOT test number	610064431122
Result	<b>X</b> Failed
Advice Rear Tyre worn close to legal limit/worn on edge both rear tyres ba	ald on inner edge (5.2.3 (e))

**DANGEROUS** Offside Front Tyre has ply or cords exposed perished and cracked on tread exposing cord (5.2.3 (d) (ii))

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**DANGEROUS** Offside Rear Tyre has ply or cords exposed cut and damage on tread exposing cord (5.2.3 (d) (ii))

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm and heavily worn inner edge (5.2.3 (e))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed perished and cracked on tread exposing cord (5.2.3 (d) (ii))

Minor Offside Rear Tyre obviously under inflated (5.2.3 (I))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #8 2022-04-14 16:20

**MOT test number** 817561859444

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2022-04-11 15:28

MOT test number 541153169412

Result X Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #6** 2021-03-30 11:43

MOT test number 413443846490

**Result** 
✓ Passed

MOT #5 2020-03-25 10:48

**MOT test number** 263575302498

Result 

Passed

MOT #4 2019-04-04 11:41

**MOT test number** 872205549749

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #3	2018-04-09 12:34
MOT test number	531328163235
Result	<b>✓</b> Passed
MOT #2	2017-04-10 13:41
MOT test number	531540923875
Result	✓ Passed
MOT #1	2016-04-14 09:37
MOT test number	247833020001
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Tax & MOT check



Days left 95

MOT expiry date 24 May 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
***********	
***************************************	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK NY
Plate since	
Current registration	OK ON THE STATE OF
Plate since	
	More info >

CarCheck.co.uk page 8/11



## Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2004-01-16
Last registration	2023-05-25
Complete history	See info



Registration #1	2004-01-16	26 mi
Registration #2	2016-04-14	46.800 mi
Registration #3	2017-04-10	51.132 mi
Registration #4	2018-04-09	55.737 mi
Registration #5	2019-04-04	61.661 mi
Registration #6	2020-03-25	64.558 mi
Registration #7	2021-03-30	67.676 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 ea
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

# Additional information

Number of seats	8
Engine number	VQ35

CarCheck.co.uk page 11/11