




report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO L1H1 2300 SPORTIVE CDTI ECOFLEX S/S
Colour	Silver
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-20
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



## MOT history

MOT expiry date	2021-12-13
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	9
Total items failed	7

MOT #4	2020-12-07 13:13
MOT test number	823266494190
Result	✓ Passed
Next expiry date	2021-12-13

MOT #3	2020-12-07 12:24
MOT test number	482568280599
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #2	2019-11-25 17:27
MOT test number	389109990826
Result	✓ Passed
Advice	No gas blast detected at time of test
Advice	Offside Rear Nail in tyre
Advice	Under trays fitted obscuring view of brake / fuel lines and other components
Advice	Nearside Rear Nail in tyre

**MOT #1**

2019-11-25 10:31

**MOT test number**

501784202935

**Result****✗ Failed****Fail** Windscreen washer not working (3.5 (a))**Advice** Offside Rear Nail in tyre**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Under trays fitted obscuring view of brake / fuel lines and other components**Fail** Nearside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** No gas blast detected at time of test**Fail** Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



Tax & MOT check

X

Untaxed

Tax expired:  
1 May 2022

X

MOT

Expired:  
13 December 2021

Tax status	Expired at 1 May 2022
Days left	728 days too late
MOT expiry date	13 December 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 EJ66FAK
Plate since	2019-06-29
Current registration	 EJ66FAK
Plate since	2019-06-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2016-12-14
Last registration	2020-12-07
Complete history	<a href="#">See info</a>



Registration #1	2016-12-14	11 mi
Registration #2	2019-11-25	30.279 mi
Registration #3	2019-11-25	30.281 mi
Registration #4	2019-11-25	30.277 mi
Registration #5	2019-11-25	30.277 mi
Registration #6	2019-11-25	30.277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1320 kg
Max. allowed weight	2320 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	330A10006275303 LN9