



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-28
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-16
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	22
Total items failed	10

MOT #16	2023-11-17 11:19
MOT test number	971665583789
Result	✓ Passed
Next expiry date	2024-11-16
Advice	Rear Unable to test rear seat belts Heavy object on the Seat

MOT #15	2022-11-08 16:39
MOT test number	699396025942
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2022-11-08 13:53
MOT test number	463622343818
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Dipswitch does not operate immediately when selected on main beam (4.1.3 (b))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #13**

2021-08-21 14:39

MOT test number

999567439753

Result

✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Items removed from driver's view prior to test**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12**

2021-08-20 15:48

MOT test number

331040746046

Result

✗ Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Items removed from driver's view prior to test**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Nail in tyre x 2 nails**MOT #11**

2020-09-15 10:07

MOT test number

795038398435

Result

✓ Passed

**MOT #10** 2019-09-21 11:18**MOT test number** 716189998013**Result** ✓ Passed**MOT #9** 2018-09-17 14:26**MOT test number** 595509239395**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2018-09-17 13:04**MOT test number** 712869886942**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2017-09-18 13:57**MOT test number** 549068900986**Result** ✓ Passed**MOT #6** 2016-09-15 08:02**MOT test number** 675132161501**Result** ✓ Passed**Advice** Rear brake pads wearing low**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' small chip (8.3.1d)

**MOT #5** 2016-09-15 08:02**MOT test number** 769395894233**Result** ✗ Failed**Advice** Rear brake pads wearing low**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' small chip (8.3.1d)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2015-09-21 07:28**MOT test number** 553939708542**Result** ✓ Passed**MOT #3** 2014-08-22 10:10**MOT test number** 248024834236**Result** ✓ Passed**MOT #2** 2014-08-22 10:10**MOT test number** 237364334272**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #1** 2013-08-29 14:15**MOT test number** 559591743226**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
16 November 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		16 November 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-05
Last registration	2023-11-17
Complete history	See info



Registration #1	2010-07-05	8 mi
Registration #2	2013-08-29	60.255 mi
Registration #3	2014-08-22	70.396 mi
Registration #4	2015-09-21	81.171 mi
Registration #5	2016-09-15	89.983 mi
Registration #6	2016-09-15	89.983 mi
Registration #7	2017-09-18	100.242 mi
Registration #8	2018-09-17	109.111 mi
Registration #9	2018-09-17	109.111 mi
Registration #10	2019-09-17	118.983 mi
Registration #11	2019-09-17	118.983 mi
Registration #12	2019-09-17	118.983 mi
Registration #13	2019-09-17	118.983 mi
Registration #14	2019-09-17	118.983 mi
Registration #15	2019-09-17	118.983 mi
Registration #16	2019-09-17	118.983 mi
Registration #17	2019-09-17	118.983 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 694229