

Ford



### General information

Take FORD	
1odel FUSION	N ZETEC CLIMATE
Silver	
Year of manufacture2008	
<b>Top speed</b> 102 m	ph
- <b>60 mph</b> 14.5 se	econds
Searbox 5 spee	d Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





# MOT history

MOT expiry date	2024-03-22
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	8
Total items failed	9

MOT #18	2023-03-23 14:43
MOT test number	663973388612
Result	✓ Passed
Next expiry date	2024-03-22
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #17	2023-03-23 11:59
MOT test number	752262528207
Result	🗙 Failed
<b>Fail</b> Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
FailNearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #16		2022-03-23 15:19
MOT test	number	163415062493
Result		✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	



YM08AVB report date: 2024-03-28

MOT #15	2022-03-23 10:15
MOT test number	878729313026
Result	🗙 Failed
<b>Fail</b> Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Offside Front Suspension arm ball joint dust cover no longer prevents the ingress o	f dirt (5.3.4 (b) (ii))

MOT #14	2021-02-26 17:01
MOT test number	391733424727
Result	✓ Passed

MOT #13	2020-05-29 15:53
MOT test number	934221323535
Result	✓ Passed

MOT #12	2020-05-29 10:20
MOT test number	106624423750
Result	🗙 Failed
<ul><li>Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</li><li>Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingr</li></ul>	ress of dirt (5.3.4 (b) (ii))

MOT #11		2019-05-28 09:42
MOT test i	number	705975802649
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing 195/60/15 (5.2.3 (d) (ii)	)



YM08AVB report date: 2024-03-28

MOT #10	2019-05-28 09:42
MOT test number	101383862475
Result	🗙 Failed
Advice Offside Front Tyre slightly damaged/cracking or perishing 195/60/15 (5.2.3 (d)	(ii))
<b>Pass with rectification</b> Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MOT #9	2018-05-31 11:50
MOT test number	375686443831
Result	✓ Passed
MOT #8	2017-03-22 09:51
MOT test number	198285419300
Result	✓ Passed
MOT #7	2016-03-22 17:05
MOT test number	360482031272
Result	✓ Passed
MOT #6	2015-03-30 10:26
MOT #8 MOT test number	925169385079
Result	✓ Passed
Result	V Tubbeu
MOT #5	2014-03-25 12:31
MOT test number	695494984088
Result	✓ Passed
MOT #4	2013-03-26 14:34
MOT test number	725555683091
Result	✓ Passed





MOT #3	2012-04-26 15:55
MOT test number	896287312110
Result	✓ Passed
MOT #2	2011-05-18 10:39
MOT test number	619958531102
Result	✓ Passed
MOT #1	2011-05-18 10:39
MOT test number	168288431159
Result	× Failed
Pass with rectification	Nearside Front Headlamp aim too high and too far to the left. (1.8)



YM08AVB report date: 2024-03-28

Tax & MOT check

X Untaxed Tax expired: 1 April 2024	<b>X</b> <b>MOT</b> Expired: 22 March 2024
Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	22 March 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-11
Last registration	2023-03-23
Complete history	See info



Registration #1	2008-07-11	28 mi
Registration #2	2011-05-18	21.315 mi
Registration #3	2012-04-26	24.570 mi
Registration #4	2013-03-26	26.580 mi
Registration #5	2014-03-25	32.258 mi
Registration #6	2015-03-30	39.873 mi
Registration #7	2016-03-22	45.012 mi
Registration #8	2017-03-22	53.157 mi
Registration #9	2018-05-31	58.317 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Max. allowed weight	1605 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	
	5
Number of seats	5 5

**Engine number** 

8E18431