



report date: 2024-03-29

General information

Make	MINI
Model	ROADSTER JOHN COOPER WORKS
Colour	Silver
Year of manufacture	2013
Top speed	145 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	211 BHP
Max. torque	260 Nm at 5.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-03
Pictures	33
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-02
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #11	2024-04-03 14:48
MOT test number	704113959049
Result	✓ Passed
Next expiry date	2025-04-02
Minor	Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge 205/4517 (5.2.3 (e))

MOT #10	2024-04-03 13:56
MOT test number	511169960503
Result	✗ Failed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge 205/4517 (5.2.3 (e))

MOT #9	2023-03-06 14:23
MOT test number	413694626733
Result	✓ Passed
Minor	Offside Windscreen damaged but not adversely affecting driver's view Stone Chip Damage (3.2 (a) (i))

**MOT #8** 2023-03-06 12:04**MOT test number** 425337750143**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view Stone Chip Damage (3.2 (a) (i))**MOT #7** 2022-02-21 15:42**MOT test number** 794212349982**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2022-02-21 14:16**MOT test number** 779385151886**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #5** 2021-03-05 15:00**MOT test number** 158867815847**Result** ✓ Passed**MOT #4** 2020-02-14 12:27**MOT test number** 350956306360**Result** ✓ Passed**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #3	2019-02-15 12:55
MOT test number	963605713644
Result	✓ Passed

MOT #2	2018-02-01 11:31
MOT test number	144431267172
Result	✓ Passed
Advice	Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Outer Tyre has a bulge but not failing overall structure of tyre.

MOT #1	2017-02-16 11:40
MOT test number	221561130063
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
2 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	2 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-29
Current registration	 XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-25
Last registration	2024-04-03
Complete history	<a href="#">See info</a>



Registration #1	2013-09-25	18 mi
Registration #2	2017-02-16	7.249 mi
Registration #3	2018-02-01	10.852 mi
Registration #4	2019-02-15	15.353 mi
Registration #5	2020-02-14	20.112 mi
Registration #6	2021-03-05	23.830 mi
Registration #7	2022-03-20	25.277 mi
Registration #8	2023-03-20	26.277 mi
Registration #9	2024-03-20	27.277 mi
Registration #10	2025-03-20	28.277 mi
Registration #11	2026-03-20	29.277 mi
Registration #12	2027-03-20	30.277 mi
Registration #13	2028-03-20	31.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3758 mm
Wheel base	2467 mm
Kerb weight	1265 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	B429J596
---------------	----------