



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE TJET
Colour	Black
Year of manufacture	2008
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-09-23
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-04
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date 2024-04-03**MOT pass rate** 68 %**MOT passed** 13**Failed MOT tests** 6**Total advice items** 35**Total items failed** 15**MOT #19** 2023-04-04 14:46**MOT test number** 664216205929**Result** ✓ Passed**Next expiry date** 2024-04-03**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #18** 2023-04-03 12:03**MOT test number** 828569935935**Result** ✗ Failed**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #17** 2022-04-01 09:22**MOT test number** 615113593248**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #16**

2022-03-25 10:35

MOT test number

237335495025

Result**✗ Failed****Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #15**

2021-03-23 12:11

MOT test number

295675850957

Result**✓ Passed****Advice** Nearside Front gearbox dog bone mount bush worn**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #14**

2021-03-19 10:46

MOT test number

681324503505

Result**✗ Failed****Fail** Rear Coil spring fractured or broken both sides (5.3.1 (b) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front gearbox dog bone mount bush worn**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Suspension arm pin or bush excessively worn both sides rear bush (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

**MOT #13** 2019-09-26 09:01**MOT test number** 750285103632**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #12** 2019-01-03 15:24**MOT test number** 696860243471**Result** ✓ Passed**MOT #11** 2018-03-28 10:16**MOT test number** 216220817333**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases pipe (7.1.2)**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush rear wishbone bush (2.5.A.1c)**MOT #10** 2018-03-27 13:49**MOT test number** 805834102362**Result** ✗ Failed**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush rear wishbone bush (2.5.A.1c)**Fail** Nearside Front Front suspension has excessive movement at a wishbone pin or bush rear wishbone bush (2.5.A.1c)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Exhaust has a minor leak of exhaust gases pipe (7.1.2)

**MOT #9** 2017-03-31 09:14**MOT test number** 505493696528**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)**Advice** General underbody corrosion**Advice** Undertrays fitted obscuring some underbody components**MOT #8** 2016-03-31 14:10**MOT test number** 872053165302**Result** ✓ Passed**MOT #7** 2016-03-31 08:24**MOT test number** 362464932517**Result** ✗ Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #6** 2015-03-31 15:33**MOT test number** 185890195024**Result** ✓ Passed**Notice** Brake fluid level below maximum**Notice** Both front brake discs lipped**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both front tyres wearing heavily on edges**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-04-01 12:51**MOT test number** 936921194093**Result** ✓ Passed**Notice** Rear tyres in poor condition ,cracking**MOT #4** 2014-03-31 09:12**MOT test number** 856120894023**Result** ✗ Failed**Notice** Rear tyres in poor condition ,cracking**Fail** Nearside Front Headlamp aim too low (1.8)**Notice** Offside rear coil spring mount missing**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2013-03-28 13:28**MOT test number** 285257283097**Result** ✓ Passed**Notice** Unable to inspect rear seat belts as unaccessible**Notice** Items removed from driver's view prior to test**MOT #2** 2012-03-29 11:29**MOT test number** 255399882061**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-03-21 13:59**MOT test number** 599630481089**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 June 2024

✗

MOT

Expired:
3 April 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	3 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-31
Last registration	2023-04-04
Complete history	See info



Registration #1	2008-03-31	13 mi
Registration #2	2011-03-21	22.744 mi
Registration #3	2012-03-29	29.548 mi
Registration #4	2013-03-28	34.673 mi
Registration #5	2014-03-31	39.784 mi
Registration #6	2014-04-01	39.794 mi
Registration #7	2015-03-31	49.097 mi
Registration #8	2016-03-31	59.428 mi
Registration #9	2016-03-31	59.428 mi
Registration #10	2017-03-31	72.786 mi
Registration #11	2018-03-27	85.436 mi
Registration #12	2019-03-31	95.000 mi
Registration #13	2020-03-31	105.000 mi
Registration #14	2021-03-31	115.000 mi
Registration #15	2022-03-31	125.000 mi
Registration #16	2023-03-31	135.000 mi
Registration #17	2024-03-31	145.000 mi
Registration #18	2025-03-31	155.000 mi
Registration #19	2026-03-31	165.000 mi
Registration #20	2027-03-31	175.000 mi
Registration #21	2028-03-31	185.000 mi
Registration #22	2029-03-31	195.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1148842