



report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2015
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-10-03
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-03
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	13

MOT #9	2023-12-12 11:39
MOT test number	272192757833
Result	✓ Passed
Next expiry date	2024-12-11

**MOT #8**

2023-12-11 14:56

**MOT test number**

308719634397

**Result****✗ Failed****Fail**

Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Fail**(4.4.1 (b) (ii))  
Nearside Rear Direction indicator lens defective such that the emitted light is adversely affected**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Fail**

Nearside Front Headlamp aim too high (4.1.2 (a))

**Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail**

Passenger's seat insecure (6.2.6 (a) (ii))

**Minor**(4.7.1 (b) (i))  
Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources**Fail**

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Advice**

Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2022-11-02 08:38

**MOT test number**

970866085081

**Result****✓ Passed****Advice**

Nearside Front Passenger seat(s) missing at time of test

**Advice**

Front Brake pad(s) wearing thin both inner pads look close to limit (1.1.13 (a) (ii))

**MOT #6** 2022-11-02 08:38**MOT test number** 837342416066**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Passenger seat(s) missing at time of test**Advice** Front Brake pad(s) wearing thin both inner pads look close to limit (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2021-10-16 10:22**MOT test number** 794731224586**Result** ✓ Passed**MOT #4** 2020-09-07 16:59**MOT test number** 886379659609**Result** ✓ Passed**MOT #3** 2019-08-23 12:36**MOT test number** 618303439557**Result** ✓ Passed**MOT #2** 2019-08-23 12:36**MOT test number** 392043007093**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))



MOT #1	2018-09-11 16:59
MOT test number	647256912244
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
11 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation


Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>FJ65ZDD</b>
Plate since	2019-03-29
Current registration	<b>FJ65ZDD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-10
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2015-09-10	14 mi
Registration #2	2018-09-11	50.228 mi
Registration #3	2019-08-23	59.029 mi
Registration #4	2019-08-23	59.029 mi
Registration #5	2020-09-07	64.166 mi
Registration #6	2020-09-07	64.166 mi
Registration #7	2020-09-07	64.166 mi
Registration #8	2020-09-07	64.166 mi
Registration #9	2020-09-07	64.166 mi
Registration #10	2020-09-07	64.166 mi
Registration #11	2020-09-07	64.166 mi
Registration #12	2020-09-07	64.166 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1673 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	JBDF0061045