





report date: 2024-03-29

General information

Make	PEUGEOT
Model	2008 ALLURE PREMIUM
Colour	Black
Year of manufacture	2018
Top speed	104 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 5

Date 2021-12-30

Pictures 19

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 4

Date 2021-12-29

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date 2021-08-13

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-08-12

Pictures 19

Listing price View report
CarCheck.co.uk page 2/11









source: autotrader.co.uk

Entry 1

Date	2021-06-06
Pictures	19
Listing price	View report









source: autotrader.co.uk



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-14
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	5
Total items failed	1

MOT #5	2023-07-15 10:49
MOT test number	234886945395
Result	✓ Passed
Next expiry date	2024-07-14
Minor Offside Registration plate lamp inoperative in the case of multiple lamp (i))	os or light sources (4.7.1 (b)

MOT #4	2023-01-31 15:32
MOT test number	113501910151
Result	✓ Passed
MOT #3	2022-01-31 18:22
MOT test number	050454400070

MOT #3	2022-01-31 18:22
MOT test number	950454480878
Result	✓ Passed

 MOT #2
 2021-05-26 09:26

 MOT test number
 267249550228

Advice Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-05-25 15:59

MOT test number 656749242733

Result X Failed

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim			
Own	or h	ist <i>i</i>	าrv
	וו וט	IJU	יוע

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-09-28
Last registration	2023-07-15
Complete history	See info



Registration #1	2018-09-28	10 mi
Registration #2	2021-05-25	19.213 mi
Registration #3	2021-05-26	19.213 mi
Registration #4		11.777 es
Registration #5		0.77 ss
Registration #6		71.777 66
Registration #7		9.777 es
Registration #8		11.777 ea
Registration #9		9.777 es
Registration #10		11.777 ea
Registration #11		11.117 es

More info >

CarCheck.co.uk page 10/11



ML68WLC report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	77%
Pedestrian	72%
Safety systems	70%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1556 mm
Length	4159 mm
Wheel base	2538 mm
Kerb weight	1045 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number XVA70111485