



report date: 2024-03-29

General information

|                     |                          |
|---------------------|--------------------------|
| Make                | NISSAN                   |
| Model               | PRIMASTAR DCI SE SHR P/V |
| Colour              | Red                      |
| Year of manufacture | 2008                     |
| Top speed           | 99 mph                   |
| Gearbox             | 6 speed Manual           |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 113 BHP             |
| Max. torque             | 300 Nm at 1.500 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 31.0 mpg            |
| Consumption extra urban | 43.5 mpg            |
| Consumption combined    | 37.7 mpg            |



LABEL UNKNOWN



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-06-08 |
| MOT pass rate      | 59 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 7          |
| Total advice items | 26         |
| Total items failed | 20         |

|                  |                  |
|------------------|------------------|
| MOT #17          | 2020-06-09 13:27 |
| MOT test number  | 875722152683     |
| Result           | ✓ Passed         |
| Next expiry date | 2021-06-08       |

|                 |                  |
|-----------------|------------------|
| MOT #16         | 2020-06-09 10:18 |
| MOT test number | 980276008877     |
| Result          | ✗ Failed         |

- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))

**MOT #15** 2019-03-29 09:31**MOT test number** 108286601080**Result** ✓ Passed

- Advice** Suspect gear box noise
- Advice** Nearside Front Nail in tyre
- Advice** Front signs of corrosion
- Advice** Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))
- Advice** Under side thick in mud

**MOT #14** 2018-04-09 06:57**MOT test number** 966944393658**Result** ✓ Passed

- Advice** Central Front Child Seat fitted not allowing full inspection of adult belt

**MOT #13** 2018-04-09 06:57**MOT test number** 706547175404**Result** ✗ Failed

- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Advice** Central Front Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2017-05-30 15:58**MOT test number** 311005111351**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' NOT IN DRIVERS VIEW (8.3.1a)

**MOT #11** 2017-05-30 15:58**MOT test number** 752680880352**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' NOT IN DRIVERS VIEW (8.3.1a)**MOT #10** 2017-03-17 08:58**MOT test number** 579764004693**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' Windscreen cracked various BUT NOT in drivers view (8.3.1a)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-03-26 09:13**MOT test number** 550245406931**Result** ✓ Passed**Advice** Windscreen cracked**MOT #8** 2015-03-14 12:33**MOT test number** 948403675031**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-03-14 09:55**MOT test number** 208813375085**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2014-03-15 13:11**MOT test number** 659964074080**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #5** 2013-03-08 16:17**MOT test number** 115387163474**Result** ✓ Passed**MOT #4** 2012-03-07 15:49**MOT test number** 316767762029**Result** ✓ Passed

**MOT #3** 2012-03-07 11:11**MOT test number** 965877562089**Result** ✗ Failed**Notice** Front wiper blades are worn.**Notice** N/s/r tyre is worn to 2mm.**Fail** Offside Front Headlamp aim too high (1.8)**Notice** N/s/f tyre is worn to 1.6mm.**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #2** 2011-03-17 16:58**MOT test number** 415346971084**Result** ✓ Passed**MOT #1** 2011-03-16 17:45**MOT test number** 465215571084**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Notice** O/s rear tyre distorting**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Centre Stop lamp not working (1.2.1b)**Notice** Front brake pads worn**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✕  
Untaxed

Tax expired:  
16 February 2021

✕  
MOT

Expired:  
8 June 2021

Tax status

Expired at 16 February 2021

Days left

1168 days too late

MOT expiry date

8 June 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

|          |  |  |
|----------|--|--|
| Damage 1 |  |  |
| Date     |  |  |
| Category |  |  |
| Type     |  |  |
| Damage 2 |  |  |
| Date     |  |  |
| Category |  |  |
| Type     |  |  |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>YG08WFH</b> |
| Plate since          | 2019-03-29     |
| Current registration | <b>YG08WFH</b> |
| Plate since          | 2019-03-29     |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 18                       |
| First mileage registration | 2008-03-14               |
| Last registration          | 2020-06-09               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2008-03-14 | 18 mi     |
| Registration #2  | 2011-03-16 | 23.630 mi |
| Registration #3  | 2011-03-17 | 23.630 mi |
| Registration #4  | 2012-03-07 | 42.207 mi |
| Registration #5  | 2012-03-07 | 42.207 mi |
| Registration #6  | 2013-03-08 | 48.917 mi |
| Registration #7  | 2014-03-15 | 60.388 mi |
| Registration #8  | 2015-03-14 | 72.541 mi |
| Registration #9  | 2015-03-14 | 72.543 mi |
| Registration #10 | 2016-03-14 | 72.543 mi |
| Registration #11 | 2016-03-14 | 72.543 mi |
| Registration #12 | 2016-03-14 | 72.543 mi |
| Registration #13 | 2016-03-14 | 72.543 mi |
| Registration #14 | 2016-03-14 | 72.543 mi |
| Registration #15 | 2016-03-14 | 72.543 mi |
| Registration #16 | 2016-03-14 | 72.543 mi |
| Registration #17 | 2016-03-14 | 72.543 mi |
| Registration #18 | 2016-03-14 | 72.543 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

|                 |                  |
|-----------------|------------------|
| Fuel delivery   | Direct Injection |
| Number of doors | 4                |
| Number of seats | 3                |
| Engine number   | 061385           |