



Mercedes-Benz




report date: 2024-03-29

## General information

Make	MERCEDES
Model	C C180K SE
Colour	Black
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J



**MOT history**

<b>MOT expiry date</b>	2021-12-21
<b>MOT pass rate</b>	76 %
<b>MOT passed</b>	13
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	17
<b>Total items failed</b>	12

**MOT #17** 2020-12-09 10:21**MOT test number** 401815940840**Result** Passed**Next expiry date** 2021-12-21

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #16** 2020-12-02 10:11**MOT test number** 390254431210**Result** Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))

**MOT #15** 2019-12-10 12:11**MOT test number** 919007914310**Result** ✓ Passed**MOT #14** 2019-11-30 09:44**MOT test number** 919755225634**Result** ✗ Failed

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Front Exhaust system insecure (6.1.2 (a))
- Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords wall (5.2.3 (d) (i))
- Fail** Offside Front Registration plate does not conform to the specified requirements (0.1 (d))
- Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords wall (5.2.3 (d) (i))

**MOT #13** 2018-11-24 09:45**MOT test number** 957283633512**Result** ✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear rear tyres cracking up
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12** 2017-12-09 10:20**MOT test number** 505727591672**Result** ✓ Passed

**MOT #11** 2016-11-26 13:41**MOT test number** 640060049586**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2015-11-28 13:22**MOT test number** 324646822041**Result** ✓ Passed**MOT #9** 2015-11-28 13:22**MOT test number** 370181455747**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2014-12-03 09:48**MOT test number** 695917034343**Result** ✓ Passed**MOT #7** 2013-12-11 12:34**MOT test number** 917145543337**Result** ✓ Passed

**MOT #6** 2013-12-10 15:40**MOT test number** 616154543324**Result** ✗ Failed**Notice** Suspected brake problem with n/s/r.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2012-12-22 14:17**MOT test number** 457137352441**Result** ✓ Passed**MOT #4** 2011-12-06 15:29**MOT test number** 859460141394**Result** ✓ Passed**MOT #3** 2011-06-24 16:56**MOT test number** 258815671160**Result** ✓ Passed**MOT #2** 2010-11-29 12:35**MOT test number** 804333730302**Result** ✓ Passed**MOT #1** 2009-11-24 11:02**MOT test number** 430468629422**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>KG56RCO</b>
Plate since	2019-03-29
Current registration	 <b>KG56RCO</b>
Plate since	2019-03-29

More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-11-29
Last registration	2020-12-09
Complete history	<a href="#">See info</a>



Registration #1	2006-11-29	13 mi
Registration #2	2009-11-24	32.740 mi
Registration #3	2010-11-29	48.176 mi
Registration #4	2011-06-24	48.393 mi
Registration #5	2011-12-06	52.453 mi
Registration #6	2012-12-22	63.028 mi
Registration #7	2013-12-10	71.338 mi
Registration #8	2013-12-11	71.355 mi
Registration #9	2014-12-03	81.768 mi
Registration #10	2015-05-20	91.377 mi
Registration #11	2015-05-20	91.377 mi
Registration #12	2015-05-20	91.377 mi
Registration #13	2015-05-20	91.377 mi
Registration #14	2015-05-20	91.377 mi
Registration #15	2015-05-20	91.377 mi
Registration #16	2015-05-20	91.377 mi
Registration #17	2015-05-20	91.377 mi
Registration #18	2015-05-20	91.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194630746967