



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Black
Year of manufacture	2007
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B





MOT history

MOT expiry date	2021-12-15
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	40
Total items failed	23

MOT #18 2020-11-20 12:19

MOT test number 539986724643

Result ✓ Passed

Next expiry date 2021-12-15

- Advice** Under-body corroded in presceibed areas
- Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Under-trays fitted
- Advice** Nearside Front Nail in tyre
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2019-12-13 10:08

MOT test number 142816401779

Result ✓ Passed

- Advice** Rear both inner sills corroded
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Subframe mounting prescribed area is corroded but not considered excessive and component (5.3.6 (a) (i))

**MOT #16** 2018-12-13 10:31**MOT test number** 672120642215**Result** ✓ Passed**Advice** Under-body corroded in prescribed areas**MOT #15** 2017-11-25 10:34**MOT test number** 622681675025**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #14** 2016-12-16 17:09**MOT test number** 643701957284**Result** ✓ Passed**MOT #13** 2016-10-20 15:28**MOT test number** 422083084856**Result** ✓ Passed**MOT #12** 2016-10-20 10:43**MOT test number** 911546973807**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #11** 2015-10-08 16:34**MOT test number** 116137338823**Result** ✓ Passed



MOT #10	2015-10-06 09:15
MOT test number	181056822124
Result	✗ Failed
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)
Fail	Nearside Rear coil spring broken (2.4.C.1a)
Fail	Offside Front wheel bearing rough when rotated (2.5.A.2)
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Offside Rear coil spring broken (2.4.C.1a)

MOT #9	2014-10-22 16:10
MOT test number	367355294222
Result	✓ Passed
Advice	Offside Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Body has slight corrosion (6.1.B.2)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Body has slight corrosion (6.1.B.2)



MOT #8	2014-10-22 15:24
MOT test number	866795394252
Result	✗ Failed
Advice	Offside Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Body has slight corrosion (6.1.B.2)
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Body has slight corrosion (6.1.B.2)
Fail	Offside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
Pass with rectification	Offside Headlamp aim too high (1.8)

MOT #7	2013-09-02 16:16
MOT test number	605215543203
Result	✓ Passed
Advice	Offside Rear Body has slight corrosion (6.1.B.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Body has slight corrosion (6.1.B.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6**

2013-08-31 14:35

MOT test number

568503843246

Result**✗ Failed**

- Advice** Offside Rear Body has slight corrosion (6.1.B.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Body has slight corrosion (6.1.B.2)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5

2012-08-17 13:50

MOT test number

769940232268

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #4

2012-08-17 13:50

MOT test number

438980932268

Result

✗ Failed

Pass with rectification

Offside Rear position lamp(s) not working (1.1.A.3b)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification

Front position lamp(s) not working (1.1.A.3b)

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #3

2011-09-02 13:23

MOT test number

867015741289

Result

✓ Passed

Notice

Front brake discs are slightly worn

Notice

Oil level below min.

Advice

Front Brake pad(s) wearing thin (3.5.1g)



MOT #22011-09-02 10:04

MOT test number326665341206

ResultX Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front brake discs are slightly worn
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Notice** Oil level below min.
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #12010-09-01 11:27

MOT test number411764140280

Result✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
26 February 2021

✕
MOT

Expired:
15 December 2021

Tax status	Expired at 26 February 2021
Days left	1158 days too late
MOT expiry date	15 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-06-22
Last registration	2020-11-20
Complete history	See info



Registration #1	2007-06-22	29 mi
Registration #2	2010-09-01	113.268 mi
Registration #3	2011-09-02	130.191 mi
Registration #4	2011-09-02	130.192 mi
Registration #5	2012-08-17	145.272 mi
Registration #6	2013-08-31	160.373 mi
Registration #7	2013-09-02	160.411 mi
Registration #8	2014-10-22	176.791 mi
Registration #9	2014-10-22	176.791 mi
Registration #10	2015-05-20	191.377 mi
Registration #11	2015-05-20	191.377 mi
Registration #12	2015-05-20	191.377 mi
Registration #13	2015-05-20	191.377 mi
Registration #14	2015-05-20	191.377 mi
Registration #15	2015-05-20	191.377 mi
Registration #16	2015-05-20	191.377 mi
Registration #17	2015-05-20	191.377 mi
Registration #18	2015-05-20	191.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NZU155719