




report date: 2024-03-28

General information

Make	VOLVO
Model	V50
Colour	Grey
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-10-18
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-17
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-22
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	38
Total items failed	20

MOT #18 2023-07-03 11:11

MOT test number 987840118088

Result ✓ Passed

Next expiry date 2024-07-22

Advice Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #17 2022-07-21 15:51

MOT test number 649309853920

Result ✓ Passed**Advice** Nearside Rear bumper damage**Advice** Front both side brake disc back plate corroded

MOT #16 2022-07-21 09:42

MOT test number 223498923442

Result ✗ Failed**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Front both side brake disc back plate corroded**Advice** Nearside Rear bumper damage

**MOT #15**

2021-07-21 08:53

MOT test number

817632418439

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2021-07-15 14:13

MOT test number

526820387348

Result

✗ Failed

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #13**

2020-07-23 08:32

MOT test number

300709506211

Result

✓ Passed



MOT #12	2018-07-18 13:38
MOT test number	688734405346
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2018-07-17 08:29
MOT test number	144987279542
Result	✗ Failed
Fail	Offside Front Outline marker lamp not working (4.2.1 (a))
Fail	Rear Exhaust system insecure (6.1.2 (a))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10	2017-07-20 14:23
MOT test number	875125586070
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened both rears corroded (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2017-07-20 09:07**MOT test number** 903292656226**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Upper Rear position lamp(s) not working (1.1.A.3b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both discs corroded (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit nail in tread (4.1.E.1)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both rears corroded (3.5.1i)**MOT #8** 2016-07-19 09:54**MOT test number** 265251584981**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #7** 2015-07-20 10:42**MOT test number** 649851205279**Result** ✓ Passed**Notice** Offside rear tyre unevenly worn**Notice** Wishbone bushes starting to split

**MOT #6**

2015-07-20 10:42

MOT test number

566311205278

Result**✗ Failed****Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Offside rear tyre unevenly worn**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Notice** Wishbone bushes starting to split**MOT #5**

2014-07-24 17:05

MOT test number

647365004232

Result**✓ Passed****Notice** Air conditioning condensor deteriorated**Notice** Additional reports listed on invoice number 6422**Notice** Small stonechips in the windscreen**Notice** Exhaust system rusty at joins and mounts**MOT #4**

2014-07-24 11:41

MOT test number

395545704286

Result**✗ Failed****Notice** Additional reports listed on invoice number 6422**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Small stonechips in the windscreen**Notice** Exhaust system rusty at joins and mounts**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Air conditioning condensor deteriorated



MOT #3	2013-07-16 12:45
MOT test number	455627493166
Result	✓ Passed

MOT #2	2012-07-20 16:28
MOT test number	507072202289
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2011-07-26 11:49
MOT test number	879017801281
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
22 July 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DK58UTL
Plate since	2019-03-28
Current registration	DK58UTL
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-05
Last registration	2023-07-03
Complete history	See info



Registration #1	2008-09-05	14 mi
Registration #2	2011-07-26	21.239 mi
Registration #3	2012-07-20	33.121 mi
Registration #4	2013-07-16	44.102 mi
Registration #5	2014-07-24	57.536 mi
Registration #6	2014-07-24	57.536 mi
Registration #7	2015-07-20	68.831 mi
Registration #8	2016-07-19	78.706 mi
Registration #9	2017-07-20	89.875 mi
Registration #10	2017-07-20	89.880 mi
Registration #11	2018-05-20	95.557 mi
Registration #12	2018-05-20	95.557 mi
Registration #13	2018-05-20	95.557 mi
Registration #14	2018-05-20	95.557 mi
Registration #15	2018-05-20	95.557 mi
Registration #16	2018-05-20	95.557 mi
Registration #17	2018-05-20	95.557 mi
Registration #18	2018-05-20	95.557 mi
Registration #19	2018-05-20	95.557 mi
Registration #20	2018-05-20	95.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 4

Engine number 143891