



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 HDI ZEST 3
Colour	Grey
Year of manufacture	2005
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-11-08
Pictures	35
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-11-07
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-24
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	70
Total items failed	30

MOT #25	2023-07-25 11:18
MOT test number	199824274963
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #24**

2023-07-25 09:13

MOT test number

185534557173

Result**✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #23

2022-07-06 09:05

MOT test number

258653846157

Result**✓ Passed**

- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #22**

2022-07-06 09:05

MOT test number

617371733107

Result

✗ Failed

- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #21

2021-07-13 10:12

MOT test number

785710255765

Result

✓ Passed

- Advice** Anti-roll bar corroded but not seriously weakened front (5.3.3 (b) (i))
- Advice** Side repeater slightly discoloured both front (4.4.3 (a))
- Advice** Anti-roll bar corroded but not seriously weakened across rear axle (5.3.3 (b) (i))
- Advice** Anti-roll bar linkage ball joint has slight play both front (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coil spring corroded both front (5.3.1 (b) (i))
- Minor** Anti-roll bar ball joint dust cover severely deteriorated both front (5.3.4 (b) (i))

MOT #20

2020-07-21 08:46

MOT test number

516611964339

Result

✓ Passed

- Advice** Side repeater slightly discoloured both (4.4.3 (a))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #19** 2019-10-30 14:32**MOT test number** 665749963278**Result** ✓ Passed**Advice** Signs of corrosion under vehicle**MOT #18** 2019-10-30 08:21**MOT test number** 578881481361**Result** ✗ Failed**Advice** Signs of corrosion under vehicle**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #17** 2018-10-12 09:10**MOT test number** 649656245014**Result** ✓ Passed**Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))**Advice** Front Oil leaking on to exhaust.**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16** 2017-10-25 08:53**MOT test number** 765819524818**Result** ✓ Passed

- Advice** Oil leak
- Advice** Front coil springs very rusty
- Advice** Front brake discs in very poor condition
- Advice** Play o/s/f anti roll bar end link
- Advice** Front brake pads look very low , unable to see the inner pads

MOT #15 2016-10-31 08:41**MOT test number** 713989674219**Result** ✓ Passed

- Advice** O/s/r tyre starting to perish in tread
- Advice** Slight bind n/s/f wheel
- Advice** Wipers poor
- Advice** Screw in n/s/r tyre
- Advice** Slight play o/s/f anti-roll bar end link

MOT #14 2015-10-13 12:35**MOT test number** 683178888874**Result** ✓ Passed

**MOT #13**

2015-10-13 07:39

MOT test number

720296353843

Result**✗ Failed**

- Fail** Nearside rear brake binding (3.7.B.1)
- Pass with rectification** Fuel tank insecure tank strap broken (7.2.1)
- Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Front Windscreen washer provides insufficient washer liquid both (8.2.3)

MOT #12

2014-10-28 12:41

MOT test number

915691104374

Result**✓ Passed**

- Notice** Front brake discs very rusty
- Notice** Damage to screen
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Rear wiper insecure-not working properly
- Notice** Rear shock bushes pulling through-no movement
- Notice** Fuel tank strap excessively rusty and broken-tank still held up with bolts

**MOT #11**

2014-10-28 09:24

MOT test number

687281504331

Result

✗ Failed

- Fail** Battery insecure (1.9.1)
- Notice** Damage to screen
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Rear wiper insecure-not working properly
- Notice** Rear shock bushes pulling through-no movement
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Notice** Fuel tank strap excessively rusty and broken-tank still held up with bolts
- Notice** Front brake discs very rusty
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10

2013-05-14 17:37

MOT test number

479954233132

Result

✓ Passed

MOT #9

2012-05-22 09:05

MOT test number

768513242198

Result

✓ Passed

- Notice** N.s. repeater bulb faded.

**MOT #8** 2012-05-22 09:05**MOT test number** 227203542469**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** N.s. repeater bulb faded.**MOT #7** 2011-05-26 17:10**MOT test number** 476516641143**Result** ✓ Passed**Notice** Chip w/screen.**MOT #6** 2011-05-25 16:27**MOT test number** 767615541167**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** O.s.f. a/roll bar link worn, chip w/screen.**Fail** Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #5** 2010-05-21 13:11**MOT test number** 621241340119**Result** ✓ Passed**Notice** Centre exhaust pipe to rear box join rusty**Notice** Dsl tank support strap rusty , os rear tyre bald on outer edge and close to mot limit , some imbalance front brakes**Notice** Chip zone a on 10mm , ns front wing repeater going white , slight play os steering rack , os front brake hose starting to perrish play os front roll bar link rod

**MOT #4** 2010-05-20 13:52**MOT test number** 220490940482**Result** ✗ Failed**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Nearside Front Exhaust system not adequately supported (7.1.1)**Notice** Dsl tank support strap rusty , os rear tyre bald on outer edge and close to mot limit , some imbalance front brakes**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Chip zone a on 10mm , ns front wing repeater going white , slight play os steering rack , os front brake hose starting to perrish play os front roll bar link rod**MOT #3** 2009-05-20 13:55**MOT test number** 253900549467**Result** ✓ Passed**Notice** Chip w/screen.**MOT #2** 2008-05-14 10:38**MOT test number** 322885538187**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2008-05-07 09:19

MOT test number

830548628158

Result		✗ Failed
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	
Fail	Front brake application uneven (3.7.B.2)	
Advice	Offside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail	Nearside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)	
Fail	Brakes imbalanced across an axle (3.7.B.5b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-05-21
Last registration	2023-07-25
Complete history	See info



Registration #1	2005-05-21	24 mi
Registration #2	2008-05-07	63.446 mi
Registration #3	2008-05-14	63.767 mi
Registration #4	2009-05-20	83.329 mi
Registration #5	2010-05-20	97.779 mi
Registration #6	2010-05-21	97.779 mi
Registration #7	2011-05-25	108.908 mi
Registration #8	2011-05-26	108.908 mi
Registration #9	2012-05-22	119.545 mi
Registration #10	2013-05-14	126.666 mi
Registration #11	2014-10-28	133.074 mi
Registration #12	2014-10-28	133.074 mi
Registration #13	2015-10-13	138.419 mi
Registration #14	2015-10-13	138.419 mi
Registration #15	2016-05-20	151.277 mi
Registration #16	2016-05-20	151.277 mi
Registration #17	2016-05-20	151.277 mi
Registration #18	2016-05-20	151.277 mi
Registration #19	2016-05-20	151.277 mi
Registration #20	2016-05-20	151.277 mi
Registration #21	2016-05-20	151.277 mi
Registration #22	2016-05-20	151.277 mi
Registration #23	2016-05-20	151.277 mi
Registration #24	2016-05-20	151.277 mi
Registration #25	2016-05-20	151.277 mi
Registration #26	2016-05-20	151.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1049 kg
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FD621220270