




report date: 2024-03-29

General information

Make	FORD
Model	KA STUDIO
Colour	Blue
Year of manufacture	2008
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Engine capacity	1.299 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-08-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	23
Total items failed	12

MOT #15	2020-08-07 11:35
MOT test number	562130934755
Result	✓ Passed
Next expiry date	2021-08-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #14**

2020-08-07 08:37

MOT test number

818747452282

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing CRACKING (5.2.3 (d) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13

2019-08-08 13:34

MOT test number

979825122928

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm worn on edges (5.2.3 (e))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))

**MOT #12**

2019-08-07 15:32

MOT test number

662704572104

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3.0mm worn on edges (5.2.3 (e))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11

2018-08-06 08:24

MOT test number

698639861527

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #10

2017-08-08 12:40

MOT test number

763316044686

Result**✓ Passed**

**MOT #9** 2017-08-08 09:14**MOT test number** 282007380226**Result** ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #8 2016-07-28 09:40**MOT test number** 140997350718**Result** ✓ Passed

- Advice** Nearside Front tyre worn on edges

MOT #7 2015-08-03 10:01**MOT test number** 866525615255**Result** ✓ Passed**MOT #6** 2014-08-07 16:06**MOT test number** 349069114430**Result** ✓ Passed**MOT #5** 2014-08-07 09:33**MOT test number** 525129414278**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



MOT #4	2013-07-09 11:09
MOT test number	129860293178
Result	✓ Passed
MOT #3	2013-07-09 11:09
MOT test number	838090593160
Result	✗ Failed
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)
MOT #2	2012-06-29 14:20
MOT test number	487661982151
Result	✓ Passed
MOT #1	2011-06-29 09:45
MOT test number	307200581125
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YY08VGX
Plate since	2019-03-29
Current registration	YY08VGX
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-06-30
Last registration	2020-08-07
Complete history	See info



Registration #1	2008-06-30	16 mi
Registration #2	2011-06-29	3.744 mi
Registration #3	2012-06-29	11.351 mi
Registration #4	2013-07-09	22.234 mi
Registration #5	2014-08-07	31.358 mi
Registration #6	2014-08-07	31.358 mi
Registration #7	2015-08-03	41.208 mi
Registration #8	2016-07-28	48.470 mi
Registration #9	2016-07-28	48.470 mi
Registration #10	2016-07-28	48.470 mi
Registration #11	2016-07-28	48.470 mi
Registration #12	2016-07-28	48.470 mi
Registration #13	2016-07-28	48.470 mi
Registration #14	2016-07-28	48.470 mi
Registration #15	2016-07-28	48.470 mi
Registration #16	2016-07-28	48.470 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	898 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	8B36812