



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX 16V URBAN FOX
Colour	Red
Year of manufacture	2006
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	161 g/km
CO2 label	G






Internet history

Entry 2


Date	2021-11-04
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-03
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-01-11
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	27
Total items failed	6

MOT #19 2024-01-12 10:12**MOT test number** 162883884529**Result** ✓ Passed**Next expiry date** 2025-01-11

- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))
- Advice** Central Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #18 2022-07-08 12:58**MOT test number** 414930332074**Result** ✓ Passed

- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing badly cracking need replacing (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension component pin or bush slightly worn trailing arm bush (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing badly cracking need replacing (5.2.3 (d) (ii))

**MOT #17** 2021-06-25 12:25**MOT test number** 966747527340**Result** ✓ Passed**Advice** Front brakes slight bind**MOT #16** 2021-06-24 11:12**MOT test number** 983846763846**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front brakes slight bind**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2020-07-15 10:49**MOT test number** 672258517496**Result** ✓ Passed**MOT #14** 2020-07-15 10:49**MOT test number** 671934281906**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #13** 2019-05-02 13:58**MOT test number** 271981230399**Result** ✓ Passed**MOT #12** 2018-05-03 16:02**MOT test number** 975459801769**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #11** 2017-05-08 08:59**MOT test number** 713755327727**Result** ✓ Passed**MOT #10** 2016-05-16 13:22**MOT test number** 437371968288**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #9** 2015-04-30 13:13**MOT test number** 157700025193**Result** ✓ Passed**Notice** N/S/R tyre 2-3mm**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2014-05-13 10:21**MOT test number** 445663834117**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #7** 2013-05-23 13:41**MOT test number** 817593143197**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2012-11-19 09:18**MOT test number** 979044222386**Result** ✓ Passed**MOT #5** 2011-11-28 15:12**MOT test number** 435232931479**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** All tyres starting to perish in the tread**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-11-28 09:23**MOT test number** 146202431368**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** All tyres starting to perish in the tread**MOT #3** 2010-12-08 13:39**MOT test number** 974602340319**Result** ✓ Passed



MOT #2	2009-12-16 11:34
MOT test number	794540859382
Result	✓ Passed

MOT #1	2008-12-18 14:16
MOT test number	190563958349
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-27
Last registration	2024-01-12
Complete history	See info



Registration #1	2006-04-27	19 mi
Registration #2	2008-12-18	7.536 mi
Registration #3	2009-12-16	11.797 mi
Registration #4	2010-12-08	16.376 mi
Registration #5	2011-11-28	24.711 mi
Registration #6	2011-11-28	24.711 mi
Registration #7	2012-11-19	32.672 mi
Registration #8	2013-05-23	36.127 mi
Registration #9	2014-05-13	40.382 mi
Registration #10	2015-04-30	44.382 mi
Registration #11	2016-05-16	48.408 mi
Registration #12	2016-05-16	48.408 mi
Registration #13	2016-05-16	48.408 mi
Registration #14	2016-05-16	48.408 mi
Registration #15	2016-05-16	48.408 mi
Registration #16	2016-05-16	48.408 mi
Registration #17	2016-05-16	48.408 mi
Registration #18	2016-05-16	48.408 mi
Registration #19	2016-05-16	48.408 mi
Registration #20	2016-05-16	48.408 mi
Registration #21	2016-05-16	48.408 mi
Registration #22	2016-05-16	48.408 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 024963