



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX TITANIUM 125
Colour	Blue
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-10
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #15 2023-08-21 09:09

MOT test number 355961621394

Result ✓ Passed

Next expiry date 2024-09-13

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn very thin on inner edge, * change A.S.A.P.* (5.2.3 (e))

Advice Rear Passenger seat(s) missing at time of test

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #14 2022-09-07 12:07

MOT test number 212925076923

Result ✓ Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2022-09-07 09:43

MOT test number

842882509042

Result

✗ Failed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Central Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-09-10 08:17

MOT test number

396161158978

Result

✓ Passed

MOT #11

2020-08-25 10:41

MOT test number

924400999282

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #10**

2019-08-16 11:03

MOT test number

416323376915

Result

✓ Passed

Advice Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #9	2018-08-16 10:15
---------------	------------------

MOT test number	718172846435
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2017-08-14 15:07
---------------	------------------

MOT test number	592303702634
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
---------------	----------------------------------------------------------------

MOT #7	2016-08-19 10:53
---------------	------------------

MOT test number	530406104003
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-08-19 10:53
---------------	------------------

MOT test number	997007954220
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
--------------------------------	---------------------------------------------------------------------------------------------------

MOT #5	2015-08-22 09:05
---------------	------------------

MOT test number	268144935259
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-09-06 11:11
---------------	------------------

MOT test number	525879844266
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-09-14 11:01
---------------	------------------

MOT test number	525737653289
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2013-05-17 12:40
MOT test number	527077633178
Result	✓ Passed

MOT #1	2013-05-17 12:40
MOT test number	917147733136
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Stop lamp not working (1.2.1b)	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 September 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-21
Last registration	2023-08-21
Complete history	See info



Registration #1	2010-06-21	26 mi
Registration #2	2013-05-17	16.620 mi
Registration #3	2013-09-14	17.652 mi
Registration #4	2014-09-06	24.511 mi
Registration #5	2015-08-22	31.610 mi
Registration #6	2016-08-19	38.057 mi
Registration #7	2016-08-19	38.057 mi
Registration #8	2017-08-14	42.437 mi
Registration #9	2018-08-14	46.817 mi
Registration #10	2019-08-14	51.197 mi
Registration #11	2020-08-14	55.577 mi
Registration #12	2021-08-14	59.957 mi
Registration #13	2022-08-14	64.337 mi
Registration #14	2023-08-14	68.717 mi
Registration #15	2023-08-14	68.717 mi
Registration #16	2023-08-14	68.717 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1825 mm
Height	1588 mm
Length	4372 mm
Wheel base	2640 mm
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9E89760