



report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE 115
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	155 Nm at 4.150 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-20
Pictures	28
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-10-31
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	4

MOT #17	2023-10-25 07:18
MOT test number	189064576367
Result	✓ Passed
Next expiry date	2024-10-31
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #16	2022-10-18 13:07
MOT test number	117148152044
Result	✓ Passed

MOT #15	2021-11-01 11:54
MOT test number	295481316634
Result	✓ Passed

**MOT #14**

2021-05-26 08:40

MOT test number

905029120796

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing badly perished (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished within tread (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing badly perished (5.2.3 (d) (ii))

MOT #13

2020-06-05 15:04

MOT test number

279287717303

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Coolant leak
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12

2020-06-05 10:50

MOT test number

529434086034

Result

✗ Failed

- Advice** Coolant leak
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2019-04-24 10:11

MOT test number

387215694878

Result

✓ Passed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Coolant low**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Power steering fluid level below minimum (2.1.5 (b) (i))**MOT #10**

2019-04-24 10:11

MOT test number

479931361186

Result

✗ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Power steering fluid level below minimum (2.1.5 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Coolant low**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2018-04-24 09:19**MOT test number** 589755283688**Result** ✓ Passed**Advice** Both front tyre's perished**Advice** Coolant leak**Advice** Centre stop light in op**MOT #8** 2017-04-26 08:04**MOT test number** 628270705724**Result** ✓ Passed**MOT #7** 2016-05-04 07:55**MOT test number** 911309112731**Result** ✓ Passed**Advice** Offside Obligatory mirror obscured but not seriously affecting the rear view Mirror glass cracked (8.1.2a)**MOT #6** 2015-04-28 14:13**MOT test number** 788088015166**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #5** 2014-04-09 16:32**MOT test number** 516499394097**Result** ✓ Passed**MOT #4** 2013-04-15 10:45**MOT test number** 757555703147**Result** ✓ Passed



MOT #3	2012-04-18 15:20
MOT test number	255579102163
Result	✓ Passed

MOT #2	2012-04-18 09:31
MOT test number	299439402433
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	

MOT #1	2011-09-14 12:28
MOT test number	685847551230
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ND58LGG
Plate since	2019-03-29
Current registration	ND58LGG
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-07
Last registration	2023-10-25
Complete history	See info



Registration #1	2008-11-07	16 mi
Registration #2	2011-09-14	17.029 mi
Registration #3	2012-04-18	18.428 mi
Registration #4	2012-04-18	19.428 mi
Registration #5	2013-04-15	20.953 mi
Registration #6	2014-04-09	23.852 mi
Registration #7	2015-04-28	26.980 mi
Registration #8	2016-05-04	29.231 mi
Registration #9	2017-04-26	31.195 mi
Registration #10	2018-04-24	32.904 mi
Registration #11	2019-05-20	35.377 mi
Registration #12	2020-05-20	37.377 mi
Registration #13	2021-05-20	39.377 mi
Registration #14	2022-05-20	41.377 mi
Registration #15	2023-05-20	43.377 mi
Registration #16	2024-05-20	45.377 mi
Registration #17	2025-05-20	47.377 mi
Registration #18	2026-05-20	49.377 mi
Registration #19	2027-05-20	51.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

7U48440