



Mercedes-Benz




report date: 2024-03-29

## General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	221 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-25
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	29
Total items failed	4

MOT #18	2023-08-03 11:26
MOT test number	573600829886
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #17	2023-08-03 09:59
MOT test number	124438730745
Result	✗ Failed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #16** 2022-08-10 10:26**MOT test number** 396305862259**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #15** 2022-08-10 08:36**MOT test number** 396558589936**Result** ✗ Failed**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn chalked (5.3.4 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2021-07-08 16:26**MOT test number** 709761785765**Result** ✓ Passed**MOT #13** 2020-08-05 08:12**MOT test number** 635348307724**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-08-01 11:36**MOT test number** 880473222202**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.5 (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #11** 2019-03-22 11:30**MOT test number** 791213826371**Result** ✓ Passed**MOT #10** 2018-03-26 08:52**MOT test number** 464074604429**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9** 2017-03-16 11:34**MOT test number** 933740680569**Result** ✓ Passed**Advice** Both front tyres wearing on inner edge**MOT #8** 2017-03-11 09:24**MOT test number** 632856864772**Result** ✗ Failed**Advice** Both front tyres wearing on inner edge**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2016-03-21 12:39**MOT test number** 165861427547**Result** ✓ Passed**MOT #6** 2015-03-09 12:34**MOT test number** 659778265030**Result** ✓ Passed

**MOT #5** 2014-03-17 10:34**MOT test number** 109956774415**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-03-18 15:39**MOT test number** 967407973042**Result** ✓ Passed**Notice** Some slight damage too nearside front side repeater .**Advice** Offside Front Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)**MOT #3** 2012-03-13 10:54**MOT test number** 299423672002**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #2** 2011-03-10 16:40**MOT test number** 488859061083**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #1	2010-03-11 09:52
MOT test number	120190570090
Result	✓ Passed
Notice	Nearside indicator lens in mirror cracked
Notice	Offside indicator lens in mirror cracked



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
9 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	9 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>KV07UBK</b>
Plate since	2019-06-29
Current registration	 <b>KV07UBK</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-14
Last registration	2023-08-03
Complete history	<a href="#">See info</a>



Registration #1	2007-03-14	23 mi
Registration #2	2010-03-11	17.852 mi
Registration #3	2011-03-10	21.280 mi
Registration #4	2012-03-13	25.341 mi
Registration #5	2013-03-18	29.736 mi
Registration #6	2014-03-17	35.712 mi
Registration #7	2015-03-09	41.403 mi
Registration #8	2016-03-21	48.739 mi
Registration #9	2017-03-11	57.892 mi
Registration #10	2017-03-16	57.892 mi
Registration #11	2018-03-20	57.892 mi
Registration #12	2019-03-20	57.892 mi
Registration #13	2020-03-20	57.892 mi
Registration #14	2021-03-20	57.892 mi
Registration #15	2022-03-20	57.892 mi
Registration #16	2023-03-20	57.892 mi
Registration #17	2024-03-20	57.892 mi
Registration #18	2025-03-20	57.892 mi
Registration #19	2026-03-20	57.892 mi
Registration #20	2027-03-20	57.892 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430836652