



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Black
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-02-03
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-14
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #12	2024-02-13 10:56
MOT test number	416005083113
Result	✓ Passed
Next expiry date	2025-02-14

MOT #11	2023-02-14 09:58
MOT test number	602076713275
Result	✓ Passed

MOT #10	2022-02-15 13:34
MOT test number	154006791472
Result	✓ Passed

MOT #9	2021-01-21 13:16
MOT test number	867378280430
Result	✓ Passed
Advice	Nearside Front Road wheel slightly distorted inner edge of rim has a flat spot (5.2.2 (c) (i))

**MOT #8** 2021-01-16 14:22**MOT test number** 878520278773**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Road wheel slightly distorted inner edge of rim has a flat spot (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge of tyre worn unevenly nearly bald (5.2.3 (e))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #7** 2020-01-31 13:37**MOT test number** 558431055398**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2020-01-25 11:45**MOT test number** 603538329816**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2019-01-22 14:50**MOT test number** 152341700807**Result** ✓ Passed

**MOT #4** 2018-01-20 16:13**MOT test number** 234419331552**Result** ✓ Passed**Advice** Front tyres devoid of tread on inner edge**Advice** Offside wiper blade split**MOT #3** 2018-01-20 11:15**MOT test number** 368748357676**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside wiper blade split**Advice** Front tyres devoid of tread on inner edge**MOT #2** 2017-02-07 16:37**MOT test number** 154587870184**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #1** 2016-02-08 16:25**MOT test number** 255273776824**Result** ✓ Passed**Advice** Upper level components covered**Advice** Under tray fitted



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-02-07
Last registration	2024-02-13
Complete history	See info



Registration #1	2013-02-07	18 mi
Registration #2	2016-02-08	46.161 mi
Registration #3	2017-02-07	63.416 mi
Registration #4	2018-01-20	82.063 mi
Registration #5	2018-01-20	82.063 mi
Registration #6	2019-01-22	98.268 mi
Registration #7	2020-01-25	101.082 mi
Registration #8	2020-01-25	101.082 mi
Registration #9	2020-01-25	101.082 mi
Registration #10	2020-01-25	101.082 mi
Registration #11	2020-01-25	101.082 mi
Registration #12	2020-01-25	101.082 mi
Registration #13	2020-01-25	101.082 mi
Registration #14	2020-01-25	101.082 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1390 kg
Max. allowed weight	1890 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	2353086
---------------	---------