





report date: 2024-03-29

General information

| Make | MERCEDES |
|---------------------|-------------------|
| Model | SL SL 55 AMG P/P |
| Colour | Black |
| Year of manufacture | 2005 |
| Top speed | 155 mph |
| 0 - 60 mph | 4.7 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 500 BHP |
|-------------------------|----------|
| Engine capacity | 5.439 сс |
| Cylinders | 8 |
| Fuel type | Petrol |
| Consumption city | 13.9 mpg |
| Consumption extra urban | 29.4 mpg |
| Consumption combined | 20.9 mpg |
| CO2 emission | 324 g/km |
| CO2 label | М |



CarCheck.co.uk page 1/16



T90KNGreport date: 2024-03-29

Internet history

Entry 1

Date 2021-07-21

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

| B 4 | \sim $-$ | | | |
|-------|------------|-----|-----|------|
| 10.71 | α | - h | sto | rv |
| 101 | () I | | 510 | II V |
| | • | | - | . , |

| MOT expiry date | 2025-03-01 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 17 |
| Failed MOT tests | 3 |
| Total advice items | 67 |
| Total items failed | 7 |

| MOT #20 | 2024-02-15 12:39 |
|---|------------------|
| MOT test number | 482107353564 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-01 |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #19 | | 2023-03-01 10:32 |
|------------|---|------------------|
| MOT test i | number | 700299599871 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c | 2)) |

| MOT #18 | 2022-02-08 11:26 |
|---|-----------------------|
| MOT test number | 383197223080 |
| Result | ✓ Passed |
| Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i)) | n excessive movement |
| Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i)) | in excessive movement |

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT test number
777351723925

Result

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #16 2021-02-12 11:24 **MOT** test number 555878006958 Result × Failed **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge NO CORDS SHOWING (5.2.3 (e)) Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) **Advice** Nearside Front Play in steering rack inner joint(s) Fail Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

CarCheck.co.uk page 4/16



report date: 2024-03-29

| MOT #15 | | 2020-02-20 14:22 |
|----------|---|------------------|
| MOT test | number | 255278031247 |
| Result | | ✓ Passed |
| Advice | Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 | (c)) |
| Advice | Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) | |
| Advice | Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c | (2) |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) | |

| MOT #14 | | 2019-02-07 10:49 |
|-------------|--|-------------------|
| MOT test | number | 101178001287 |
| Result | | ✓ Passed |
| Advice | Offside Front Offside Front Track rod end ball joint has slight play. | |
| Advice | Offside Rear Offside rear brake flexi hose slightly deteriorated. | |
| Advice | Offside front side repeater damaged, but still visible from a reasonable distance | |
| Advice | Nearside Front Nearside front lower suspension ball joint has slight play, push in | ball joint. |
| Advice | Nearside Rear Nearside rear brake flexi hose slightly deteriorated. | |
| Advice (c)) | Offside Front Brake pipe corroded, covered in grease or other material Slightly of | corroded. (1.1.11 |

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #13 2018-02-13 10:07 **MOT test number** 652277835144 Result ✓ Passed Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f) Front wipers slightly smearing. Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d) Advice Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d) Advice Offside Front Offside Side repeater damaged, but still visible from a reasonable distance.

| MOT #12 | 2017-02- | -07 15:32 |
|----------|--|-----------|
| MOT test | number 49671 | 8368468 |
| Result | | ✓ Passed |
| Advice | Offside Front Track rod end ball joint has slight play (2.2.B.1f) | |
| Advice | Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e) | |

| MOT #11 | | 2016-02-01 12:46 |
|----------|---|-------------------|
| MOT test | number | 547885493881 |
| Result | | ✓ Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1 | i) |
| Advice | Offside Front Side repeater damaged, but still visible from a reasonable di | stance (1.4.A.2e) |
| Advice | Offside Front Track rod end ball joint has slight play (2.2.B.1f) | |
| Advice | Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i |) |

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT test number

288253545039

Result

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Notice Offside rear brake pads starting to wear low

Notice Both front brake disc inner surfaces corroded slightly

Notice Both front seat belts slow to retract

| MOT #9 | | 2014-01-24 14:20 |
|----------|--|------------------|
| MOT test | number | 319154724024 |
| Result | | ✓ Passed |
| Notice | Under-trays fitted obscuring some underside components | |
| Notice | Engine covers fitted obscuring some components in the engine bay | |

| MOT #8 | number | 2013-02-05 10:11 |
|--------|--|------------------|
| Result | iumber | ✓ Passed |
| Notice | Nail in nearside rear tyre | |
| Advice | Nearside Inner Front brake disc worn, pitted or scored, but not seriously weal | kened (3.5.1i) |
| Advice | Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Lower Ball joint has slight play (2.2.B.1f) | |
| Advice | Offside Inner Front brake disc worn, pitted or scored, but not seriously weake | ened (3.5.1i) |
| Advice | Offside Front Track rod end ball joint has slight play (2.2.B.1f) | |

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT #7 2013-02-01 12:24 MOT test number 737792433087

Result × Failed

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Fail Offside Front Torque/reaction arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Advice Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Nail in nearside rear tyre

Advice Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Advice Nearside Front Lower Ball joint has slight play (2.2.B.1f)

Notice Oil leak

Advice Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2012-02-01 12:44

MOT test number 719392332090

Result ✓ Passed

MOT #5 2011-02-11 13:50

MOT test number 326442341070

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/16



report date: 2024-03-29

MOT #4 2011-02-09 15:31 506880541070 **MOT** test number Result × Failed **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Front registration plate letter/figure incomplete (6.3.1c) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Fail**

 MOT #3
 2010-02-12 15:40

 MOT test number
 600993840045

 Result
 ✓ Passed

MOT #2

MOT test number

2009-02-26 11:04

200987759098

Result

✓ Passed

MOT #1 2008-02-29 16:56

MOT test number 152310868055

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Small,surface cracks in Left & right Front Discs

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 9/16



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 1 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 10/16



T90KNG report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Category
Type

Damage 2

Category

Date

Туре



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner. | |
|---|-------------|
| ******** | |
| | |
| *************************************** | |
| ******** | |
| | |
| ************ | |
| | More info > |
| Plate changes See in this check if this MERCEDES had different number plates. | |
| Number of plates | , |
| Current registration | UK SIP |
| Plate since | |
| Current registration | OK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 13/16



T90KNG report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 14/16



T90KNGreport date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2005-03-01 |
| Last registration | 2024-02-15 |
| Complete history | See info |



| Registration #1 | 2005-03-01 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2008-02-29 | 29.145 mi |
| Registration #3 | 2009-02-26 | 37.153 mi |
| Registration #4 | 2010-02-12 | 42.665 mi |
| Registration #5 | 2011-02-09 | 48.212 mi |
| Registration #6 | 2011-02-11 | 48.212 mi |
| Registration #7 | 2012-02-01 | 52.316 mi |
| Registration #8 | 2013-02-01 | 56.403 mi |
| Registration #9 | 2013-02-05 | 56.403 mi |
| Registration #10 | 2014-01-24 | 57.847 mi |
| Registration #11 | 2015-02-12 | 58.393 mi |
| Registration #12 | | 71.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.177 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.177 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 9.372 es |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.777 es |

More info >

CarCheck.co.uk page 15/16



T90KNGreport date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1815 mm |
|------------|---------|
| Height | 1295 mm |
| Length | 4535 mm |
| Wheel base | 2560 mm |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 5 |
| Engine number | 11399260039077 |

CarCheck.co.uk page 16/16