



General information

Make	MINI
Model	COOPER SD
Colour	Black
Year of manufacture	2015
Top speed	141 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	360 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	B






## Internet history

### Entry 4


Date	2022-03-09
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 3

Date	2022-01-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 2

Date	2021-12-05
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-12-03
------	------------

Pictures	0
----------	---

Listing price	<a href="#">View report</a>
---------------	-----------------------------

**source:** heycar.co.uk



MOT history

MOT expiry date	2024-12-05
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	5
Total items failed	0

MOT #7	2023-11-18 09:59
MOT test number	801675244180
Result	✓ Passed
Next expiry date	2024-12-05

MOT #6	2022-12-03 11:47
MOT test number	337586797151
Result	✓ Passed

MOT #5	2021-12-06 12:57
MOT test number	358896866052
Result	✓ Passed

MOT #4	2021-03-04 16:03
MOT test number	796725071118
Result	✓ Passed

MOT #3	2020-03-06 14:19
MOT test number	843593563925
Result	✓ Passed



MOT #2	2019-07-12 15:07
MOT test number	686477849562
Result	✗ Failed
<div><div>DANGEROUS</div><div>Nearside Rear Tyre has ply or cords damaged deep cut (5.2.3 (d) (ii))</div></div>	
<div><div>Advice</div><div>Front Registration plate deteriorated but not likely to be misread minor damage (0.1 (b))</div></div>	
<div><div>Minor</div><div>Offside Front Windscreen wiper blade defective rubber splitting (3.4 (b) (i))</div></div>	
<div><div>Advice</div><div>Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div></div>	
<div><div>MAJOR</div><div>Nearside Front Road wheel fixing missing bolt missing (5.2.1 (a) (i))</div></div>	

MOT #1	2018-05-21 08:51
MOT test number	595690710976
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
5 December 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	5 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-12
Last registration	2023-11-18
Complete history	<a href="#">See info</a>



Registration #1	2015-05-12	14 mi
Registration #2	2018-05-21	34.763 mi
Registration #3	2019-07-12	41.158 mi
Registration #4	2020-03-06	41.655 mi
Registration #5	2021-03-04	48.994 mi
Registration #6	2022-03-20	55.277 mi
Registration #7	2022-03-20	55.277 mi
Registration #8	2022-03-20	55.277 mi
Registration #9	2022-03-20	55.277 mi
Registration #10	2022-03-20	55.277 mi
Registration #11	2022-03-20	55.277 mi
Registration #12	2023-11-18	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3850 mm
Wheel base	2495 mm
Kerb weight	1235 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
-----------------	---

<b>Number of axles</b>	2
<b>Engine number</b>	64399310