





report date: 2024-03-28

### General information

Make	FORD
Model	TRANSIT 280 MWB SHR P/V 85
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-01-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	9
Total items failed	17

MOT #13	2023-01-28 11:14
MOT test number	531050876803
Result	✓ Passed
Next expiry date	2024-01-27
Advice Front Brake pipe corroded, covered in grease or other material b	poth front brake pipes (1.1.11 (c))

MOT #	12	2023-01-26 15:03
MOT te	st number	877349761930
Result		<b>×</b> Failed
Fail	Front Anti-roll bar linkage ball joint excessively worn both (5.3.4 (a) (i))	
Fail	Rear Stop lamp(s) all not working (4.3.1 (a) (iii))	
Fail Nearside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting few holes due to corrosion (6.2.2 (d) (i))		
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))	
Advid	Front Brake pipe corroded, covered in grease or other material both front brak	ce pipes (1.1.11 (c))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 2/12



**MOT #11** 2021-01-16 11:21

**MOT test number** 378157378702

**Result** ✓ Passed

**MOT #10** 2021-01-16 11:21

**MOT test number** 749418539006

Result X Failed

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps

(4.7.1 (b) (ii))

MOT #9 2020-01-23 09:46

MOT test number 809501054143

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.00 mm (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

MOT #8 2020-01-21 09:05

MOT test number 815900403581

**Result** X Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.00 mm (5.2.3 (e))

CarCheck.co.uk page 3/12



**MOT** test number

YR11LXU report date: 2024-03-28

543495961381

MOT test number

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

(b) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

 MOT #6
 2018-02-03 09:40

 MOT test number
 936135500121

 Result
 ✓ Passed

 MOT #5
 2018-02-03 09:40

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b) 

X Failed

✓ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

**Pass with rectification** Central Stop lamp not working (1.2.1b)

MOT #4 2017-01-20 09:05

MOT test number 762374572379

Result ✓ Passed

 MOT #3
 2015-05-30 09:18

 MOT test number
 705760955127

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



MOT test number

Result

Pass with rectification

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification

Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

 MOT #1
 2014-03-08 08:59

 MOT test number
 455857564029

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Days left 247

MOT expiry date 27 January 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NIK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-24
Last registration	2023-01-28
Complete history	See info



Registration #1	2011-03-24	25 mi
Registration #2	2011 03 2 1	23 1111
Registration #2	2014-03-08	36.394 mi
Registration #3	2015-05-30	44.783 mi
Registration #4	2017-01-20	57.041 mi
Registration #5	2018-02-03	67.741 mi
Registration #6	2018-02-03	67.741 mi
Registration #7	2019-01-26	79.625 mi
Registration #8		11.177 es
Registration #9		11.777 mi
Registration #10		11.777 ea
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 11/12



### Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

# Dimensions & weight

Width	2360 mm
Height	2532 mm
Length	5230 mm
Max. allowed weight	2800 kg

### Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BY63554

CarCheck.co.uk page 12/12