



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS VALVEMATIC T4
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	10.0 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	150 BHP
Max. torque	196 Nm at 4.200 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-26
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	60
Total items failed	11

MOT #19	2024-02-23 13:06
MOT test number	771631017638
Result	✓ Passed
Next expiry date	2025-02-22
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-02-23 11:53
MOT test number	407246869839
Result	✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-02-23 11:53

MOT test number

959568985800

Result**✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16

2022-02-12 08:33

MOT test number

689092942157

Result**✓ Passed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

2022-02-05 10:16

MOT test number

548632286873

Result**✗ Failed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #14**

2021-01-19 09:58

MOT test number

821240544143

Result

✓ Passed

- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #13

2019-07-22 11:07

MOT test number

147165169334

Result

✓ Passed

- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))
- Advice** Under vehicle cover fitted

MOT #12

2019-07-19 09:55

MOT test number

415804230294

Result

✗ Failed

- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Under vehicle cover fitted
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement Both Sides (5.3.4 (a) (i))

MOT #11

2018-07-12 10:31

MOT test number

204831139618

Result

✓ Passed



MOT #10	2018-07-12 08:20
MOT test number	618204661857
Result	✗ Failed
 DANGEROUS Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #9	2017-07-25 09:28
MOT test number	701343524393
Result	✓ Passed
 Advice Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #8	2016-06-14 07:41
MOT test number	706542007199
Result	✓ Passed
 Advice Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)	

MOT #7	2016-06-10 08:54
MOT test number	911173501891
Result	✗ Failed
 Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
 Fail Offside Registration plate lamp not working (1.1.C.1d)	
 Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
 Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
 Fail Obligatory mirror is incapable of being adjusted to provide an adequate view to the rear (8.1.2b)	
 Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
 Advice Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)	
 Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

**MOT #6**

2015-07-03 16:20

MOT test number

707074285114

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Both rear tyres are deteriorated**MOT #5**

2015-07-03 10:05

MOT test number

636414885191

Result

✗ Failed

Notice Both rear tyres are deteriorated**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Both front wiper blades smearing screen**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4**

2014-07-16 12:27

MOT test number

549597894196

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** O/s/r tyre uneven tread**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/r tyre uneven tread

**MOT #3** 2013-07-15 12:43**MOT test number** 706446293173**Result** ✓ Passed

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2012-07-25 15:38**MOT test number** 855287602212**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-07-25 11:46**MOT test number** 989687002234**Result** ✗ Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-07
Last registration	2024-02-23
Complete history	See info



Registration #1	2009-10-07	6 mi
Registration #2	2012-07-25	30.337 mi
Registration #3	2012-07-25	30.337 mi
Registration #4	2013-07-15	43.477 mi
Registration #5	2014-07-16	56.903 mi
Registration #6	2015-07-03	66.631 mi
Registration #7	2015-07-03	66.631 mi
Registration #8	2016-06-10	76.904 mi
Registration #9	2016-06-14	76.904 mi
Registration #10	2017-07-25	91.841 mi
Registration #11	2018-07-12	105.830 mi
Registration #12	2019-06-20	121.277 mi
Registration #13	2019-06-20	121.277 mi
Registration #14	2019-06-20	121.277 mi
Registration #15	2019-06-20	121.277 mi
Registration #16	2019-06-20	121.277 mi
Registration #17	2019-06-20	121.277 mi
Registration #18	2019-06-20	121.277 mi
Registration #19	2019-06-20	121.277 mi
Registration #20	2019-06-20	121.277 mi
Registration #21	2019-06-20	121.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4695 mm
Wheel base	2700 mm
Kerb weight	1475 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	3ZRA264870