



S008RDZ

report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Red
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-05
Pictures	10
Listing price	View report



source: yesauto.com

**MOT history**

MOT #16	2021-11-08 11:50
MOT test number	156602602466
Result	✓ Passed
Next expiry date	2022-11-07

MOT #15	2021-11-02 08:38
MOT test number	962078602783
Result	✗ Failed

- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- MAJOR** Nearside Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #14**

2021-10-26 09:35

MOT test number

875830613300

Result**✗ Failed****MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Front subframe corroded**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Slight oil leak**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Engine stabilizer link deteriorated**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #13**

2020-10-29 10:15

MOT test number

784563949797

Result**✓ Passed****Advice** Exhaust has a minor leak of exhaust gases centre join sleeve (6.1.2 (a))

**MOT #12**

2019-10-23 12:36

MOT test number

369255962148

Result

✓ Passed

Advice

Wipers catching.

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Exhaust has a minor leak of exhaust gases sleeve behind flexi and rear joint. (6.1.2 (a))

MOT #11

2019-10-22 15:55

MOT test number

648802257369

Result

✗ Failed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Exhaust has a minor leak of exhaust gases sleeve behind flexi and rear joint. (6.1.2 (a))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Wipers catching.

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #10

2018-10-18 08:48

MOT test number

532844849481

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases flexi section of exhaust slight blow but ok. (6.1.2 (a))

MOT #9

2017-10-19 17:01

MOT test number

159299036204

Result

✓ Passed

**MOT #8** 2016-10-19 15:02**MOT test number** 289397610784**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-10-24 12:56**MOT test number** 527588941872**Result** ✓ Passed**MOT #6** 2014-11-26 10:56**MOT test number** 737870734321**Result** ✓ Passed**MOT #5** 2014-11-24 12:30**MOT test number** 358238624366**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2014-01-15 08:16**MOT test number** 706705514085**Result** ✓ Passed**MOT #3** 2013-01-12 09:21**MOT test number** 247642113099**Result** ✓ Passed**MOT #2** 2012-01-18 19:00**MOT test number** 958698812062**Result** ✓ Passed



MOT #1	2011-07-13 14:49
MOT test number	445564091194
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-08-25
Last registration	2021-11-08
Complete history	See info



Registration #1	2008-08-25	20 mi
Registration #2	2011-07-13	26.473 mi
Registration #3	2012-01-18	29.698 mi
Registration #4	2013-01-12	36.335 mi
Registration #5	2014-01-15	46.809 mi
Registration #6	2014-11-24	54.122 mi
Registration #7	2014-11-26	54.122 mi
Registration #8	2015-10-24	60.710 mi
Registration #9	2016-10-19	66.058 mi
Registration #10	2016-10-19	66.058 mi
Registration #11	2016-10-19	66.058 mi
Registration #12	2016-10-19	66.058 mi
Registration #13	2016-10-19	66.058 mi
Registration #14	2016-10-19	66.058 mi
Registration #15	2016-10-19	66.058 mi
Registration #16	2016-10-19	66.058 mi
Registration #17	2016-10-19	66.058 mi
Registration #18	2016-10-19	66.058 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1267536