





report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320L CDI
Colour	Silver
Year of manufacture	2009
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.6 mpg
CO2 emission	223 g/km
CO2 label	K



CarCheck.co.uk page 1/16



report date: 2024-03-28


Internet history

Entry 1

Date 2021-07-24

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-12
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	38
Total items failed	12

MOT #25		2023-05-13 16:55
MOT test	number	467062422922
Result		✓ Passed
Next expi	ry date	2024-05-12
Advice	Front Wheel bearing has slight play both (5.1.3 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #24	2022-05-04 15:10
MOT test number	580259659502
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Undertrays fitted	
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #23 2022-04-20 14:53 **MOT** test number 927881949157 Result × Failed **MAJOR** Nearside Rear Rear fog lamp not working (4.5.1 (a) (ii)) **Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Undertrays fitted Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Coolant leak Nearside Front Headlamp light intensity severely reduced (4.1.4 (a)) **MAJOR** Advice Air suspension pipe broken **Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #22

MOT test number

352274838321

Result

Advice Front Wheel bearing has slight play both side (5.1.3 (a) (i))

MOT #21

MOT test number

Serial Seri

 MOT #20
 2020-01-28 17:24

 MOT test number
 612529199680

 Result
 ✓ Passed

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #19 2018-10-29 14:45

MOT test number 598339733868

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18 2018-10-29 11:53

MOT test number 994982069884

Result X Failed

MAJOR Nearside Side repeater not working (4.4.1 (a) (ii))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2018-05-12 10:05

MOT test number 275144441503

Result
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' damaged in multiple places (8.3.1d)

Advice Coolant leak

Advice Nearside Front tyre worn on inner edge

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #16 2018-04-24 11:48 709597172399 **MOT** test number Result × Failed Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i) Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i) Fail Emissions not tested due to excessive smoke (7.3.A.1) Fail Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b) Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) **Advice Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1) Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i) Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i) Advice Coolant leak

MOT #15	2017-05-09 11:32
MOT test number	829228897511
Result	✓ Passed
MOT #14	2017-01-14 10:43
MOT test number	310142656264
Result	✓ Passed
MOT #13	2016-04-12 10:16
MOT test number	269918086999
Result	✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT test number
928865345046

Result

Notice
Nearside and offside front brake discs worn

Advice
Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice
(1.7.5a)

Nearside Headlamp has a product on the light source but not seriously reducing light output

MOT #11	2014-09-06 13:05
MOT test number	925179144224
Result	✓ Passed
MOT #10	2014-09-06 12:52
MOT test number	735269944265
Result	× Failed
Fail Offside Headlamp aim not tested (1.8.A.1c)	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	

Fail Offside Headlamp not working on dipped beam (1.7.5a)	
MOT #9	2014-01-22 12:59
MOT test number	366532524093
Result	✓ Passed
MOT #8	2013-07-30 17:48
MOT test number	337341713255
Result	✓ Passed
MOT #7	2013-02-18 11:59

MOT #7	2013-02-18 11:59
MOT test number	807619843040
Result	✓ Passed

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #6 2012-07-07 09:13

MOT test number 596458682117

Result
✓ Passed

MOT #5 2010-12-10 13:11

MOT test number 142694140391

Result X Failed

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2010-12-10 13:11

MOT test number 820674440355

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2010-06-01 16:42

MOT test number 273042150127

Result

Passed

MOT #2 2010-05-27 14:02

MOT test number 912217740100

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #1

MOT test number

Fesult

Notice Brake fluid level low

2010-04-30 08:59

500290620172

✓ Passed

CarCheck.co.uk page 9/16





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

o micr mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo here.	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2009-03-09
Last registration	2023-05-13
Complete history	See info



Registration #1	2009-03-09	27 mi
Registration #2	2010-04-30	21.487 mi
Registration #3	2010-05-27	21.518 mi
Registration #4	2010-06-01	21.518 mi
Registration #5	2010-12-10	38.501 mi
Registration #6	2012-07-07	47.707 mi
Registration #7	2013-02-18	51.159 mi
Registration #8	2013-07-30	66.943 mi
Registration #9	2014-01-22	83.961 mi
Registration #10	2014-09-06	97.345 mi
Registration #11	2014-09-06	97.345 mi
Registration #12	2015-02-14	119.504 mi
Registration #13	2016-04-12	131.095 mi
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		77.777 au

CarCheck.co.uk page 15/16



report date: 2024-03-28

Safety ratings

		大 食
--	--	------------

Video <u>see crash video</u>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3165 mm
Kerb weight	2010 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040784983

CarCheck.co.uk page 16/16