



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI BLUEMOTIONTECHNOLOGY
Colour	Silver
Year of manufacture	2011
Top speed	117 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	11.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-06
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-08
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	27
Total items failed	1

MOT #12 2024-04-17 08:29

MOT test number 496439355934

Result ✓ Passed

Next expiry date 2025-05-08

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Exhaust has a minor leak of exhaust gases sleeve corroded (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11 2023-04-18 08:19

MOT test number 464641107621

Result ✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2022-05-09 11:01

MOT test number

479598150596

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #9

2020-11-06 13:32

MOT test number

390191382651

Result

✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

MOT #8

2020-11-06 11:19

MOT test number

359672024004

Result

✗ Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect light misting of oil (5.3.2 (b))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7** 2019-05-01 14:15**MOT test number** 367577953279**Result** ✓ Passed**MOT #6** 2018-05-10 14:21**MOT test number** 975394129395**Result** ✓ Passed**MOT #5** 2017-05-12 10:00**MOT test number** 542200594744**Result** ✓ Passed**MOT #4** 2016-05-13 13:38**MOT test number** 258457861556**Result** ✓ Passed**MOT #3** 2015-05-13 15:40**MOT test number** 558683235157**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Offside wiper split.**Notice** Under-trays fitted obscuring some underside components**Notice** Both rear tyres perishing.**MOT #2** 2014-05-15 19:06**MOT test number** 626445834176**Result** ✓ Passed



MOT #1	2014-02-19 09:59
MOT test number	247170454095
Result	✓ Passed
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
8 May 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 Y222JSM
Plate since	2023-03-28
Current registration	 Y222JSM
Plate since	2023-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-02-25
Last registration	2024-04-17
Complete history	See info



Registration #1	2011-02-25	20 mi
Registration #2	2014-02-19	29.865 mi
Registration #3	2014-05-15	31.390 mi
Registration #4	2015-05-13	34.111 mi
Registration #5	2016-05-13	36.622 mi
Registration #6	2017-05-12	39.136 mi
Registration #7	2018-05-10	44.216 mi
Registration #8	2019-05-09	50.277 mi
Registration #9	2020-05-08	56.338 mi
Registration #10	2021-05-07	62.399 mi
Registration #11	2022-05-06	68.460 mi
Registration #12	2023-05-05	74.521 mi
Registration #13	2024-04-17	80.582 mi
Registration #14	2024-04-17	80.582 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm
Wheel base	2511 mm
Kerb weight	1240 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles

2

Engine number

CAY 587210
