



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Black
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN

**MOT history**

MOT #15	2022-04-06 11:35
MOT test number	718831205892
Result	✓ Passed
Next expiry date	2023-04-05
Advice Oil leak-exhaust corroded-brake flexi ferroles corroded-wishbone bushes deteriorated-front suspension arms corroded-front plate deteriorated-front brake discs corroded/worn low-	
Advice N/s/f inner arm and track rod end slight play-n/s/r tyre deflated-o/s/f cv boot deteriorated-both front tyres on limit-rear shockers corroded-	

MOT #14	2021-03-19 16:51
MOT test number	122896191168
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))	
Advice Exhaust brackets broken	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

**MOT #13**

2021-03-19 13:13

MOT test number

811659514028

Result

✗ Failed

- Advice** Nearside Front Play in steering rack inner joint(s)
- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Exhaust brackets broken
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12

2020-03-07 13:12

MOT test number

338489498420

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11

2019-03-23 12:52

MOT test number

842496684160

Result

✓ Passed

- Advice** Play in steering rack inner joint(s)

**MOT #10** 2018-03-17 13:13**MOT test number** 527875797308**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #9** 2018-03-17 09:40**MOT test number** 808631793520**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Play in steering rack inner joint(s)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #8** 2017-03-25 11:46**MOT test number** 173615334135**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #7** 2016-03-19 09:19**MOT test number** 691001478617**Result** ✓ Passed**MOT #6** 2015-03-06 16:44**MOT test number** 967375765007**Result** ✓ Passed**Notice** Wear in rear brake discs**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-03-01 10:53**MOT test number** 175370264467**Result** ✓ Passed**Notice** Some wear in front brake discs**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Play in steering rack inner joint(s)**MOT #4** 2013-03-13 14:01**MOT test number** 158292273072**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #3** 2012-03-28 16:53**MOT test number** 605758382064**Result** ✓ Passed**MOT #2** 2011-03-09 10:08**MOT test number** 156928461086**Result** ✓ Passed**Notice** Front brake pads low**MOT #1** 2010-03-30 11:16**MOT test number** 403829480004**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-30
Last registration	2022-04-06
Complete history	See info



Registration #1	2007-03-30	19 mi
Registration #2	2010-03-30	32.966 mi
Registration #3	2011-03-09	44.340 mi
Registration #4	2012-03-28	53.986 mi
Registration #5	2013-03-13	62.933 mi
Registration #6	2014-03-01	69.457 mi
Registration #7	2015-03-06	73.831 mi
Registration #8	2016-03-19	79.550 mi
Registration #9	2016-03-19	79.550 mi
Registration #10	2016-03-19	79.550 mi
Registration #11	2016-03-19	79.550 mi
Registration #12	2016-03-19	79.550 mi
Registration #13	2016-03-19	79.550 mi
Registration #14	2016-03-19	79.550 mi
Registration #15	2016-03-19	79.550 mi
Registration #16	2016-03-19	79.550 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1699 mm
Height	1420 mm
Length	4129 mm
Wheel base	2625 mm
Kerb weight	1175 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D126283