



report date: 2024-03-28

General information

Make	BMW
Model	220 220D XDRIVE M SPORT GRAN TOURER
Colour	White
Year of manufacture	2016
Top speed	135 mph
0 - 60 mph	7.8 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-25
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-23
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	23
Total items failed	13

MOT #11	2024-04-24 10:20
---------	------------------

MOT test number	232919018911
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-04-23
------------------	------------

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush split (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement split rear bush (5.3.4 (a) (i))



MOT #10

2024-04-17 16:10

MOT test number

704968694397

Result

✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement split rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush split (5.3.4 (a) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #9

2024-04-09 13:50

MOT test number

628020090100

Result

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone bush (rear) (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Front Headlamp not working on dipped beam both sides (4.1.1 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear rear bumper and tailgate damaged

MOT #8

2023-04-10 11:58

MOT test number

933003134235

Result

✓ Passed

**MOT #7** 2023-04-07 11:33**MOT test number** 863778939314**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #6** 2022-06-24 11:36**MOT test number** 527086952565**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2021-07-16 09:35**MOT test number** 907158079444**Result** ✓ Passed**MOT #4** 2020-06-15 16:13**MOT test number** 342776109917**Result** ✓ Passed**MOT #3** 2020-06-10 12:06**MOT test number** 446630608726**Result** ✗ Failed**Fail** Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #2** 2019-06-20 11:52**MOT test number** 146244260328**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #1** 2019-06-20 10:28**MOT test number** 713369475179**Result** ✗ Failed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Both front brake discs corroded/worn**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 April 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	YF16RZS
Plate since	2015-05-29
Current registration	YF16RZS
Plate since	2015-05-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-06-21
Last registration	2024-04-24
Complete history	See info



Registration #1	2016-06-21	9 mi
Registration #2	2019-06-20	44.027 mi
Registration #3	2019-06-20	44.027 mi
Registration #4	2020-06-10	55.312 mi
Registration #5	2020-06-15	55.398 mi
Registration #6	2020-06-20	55.398 mi
Registration #7	2021-07-16	64.736 mi
Registration #8	2021-07-20	64.736 mi
Registration #9	2021-07-20	64.736 mi
Registration #10	2021-07-20	64.736 mi
Registration #11	2021-07-20	64.736 mi
Registration #12	2021-07-20	64.736 mi
Registration #13	2021-07-20	64.736 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1615 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	75979506