





report date: 2024-03-29

General information

| Make | FIAT |
|---------------------|----------------|
| Model | PANDA POP |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 99 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 69 BHP |
|-------------------------|---------------------|
| Max. torque | 102 Nm at 3.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

| Date | 2021-01-29 |
|----------|------------|
| Pictures | 0 |

Listing price <u>View report</u>

source: autoonline.co.uk

Entry 1

| Date | 2021-01-21 |
|---------------|--------------------|
| Pictures | 25 |
| Listing price | <u>View report</u> |









source: yesauto.com

CarCheck.co.uk page 2/11



WM15DFY report date: 2024-03-29

MOT history

| MOT expiry date | 2025-01-03 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| MOT #8 | 2023-12-08 10:21 |
|---|----------------------------------|
| MOT test number | 204189384768 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-03 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn mo | ore so on inner edge (5.2.3 (e)) |

| MOT #7 | 2022-12-09 12:43 |
|---|------------------|
| MOT test number | 186755052913 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #6 | 2021-12-16 09:58 |
|-----------------|------------------|
| MOT test number | 470640137796 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-01-04 12:42 |
| MOT test number | 112425909366 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4

MOT test number

Result

Advice Both front tyres wearing slightly on inner and outer edges

2020-07-13 10:56

373962673846

✓ Passed

MOT #3

MOT test number

Fasult

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Both front tyres wearing slightly on inner and outer edges

MOT #2

MOT test number

Result

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

| MOT #1 | 2018-07-02 09:04 |
|-----------------|------------------|
| MOT test number | 580895909566 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 3 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
|---|-------------|
| | |
| ********* | |
| | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-07-13 |
| Last registration | 2023-12-08 |
| Complete history | See info |



| Registration #1 | 2015-07-13 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-07-02 | 14.295 mi |
| Registration #3 | 2019-07-04 | 22.381 mi |
| Registration #4 | 2020-07-13 | 27.546 mi |
| Registration #5 | 2020-07-13 | 27.546 mi |
| Registration #6 | 2021-01-04 | 29.769 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 0.00 44 |
| Registration #11 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 82% |
| Children | 63% |
| Pedestrian | 49% |
| Safety systems | 43% |
| Overall rating | 68% |
| Video | see crash video |



Dimensions & weight

| Width | 1643 mm |
|---------------------|---------|
| Height | 1551 mm |
| Length | 3653 mm |
| Wheel base | 2300 mm |
| Kerb weight | 1015 kg |
| Max. allowed weight | 1420 kg |

Additional information

| Fuel tank capacity | 37 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 4 page 11/11 |

Number of axles2Engine number1319980