



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA LIFE
Colour	Black
Year of manufacture	2015
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-03-07
Pictures	0
Listing price	View report

source: yesauto.com



MOT history

MOT expiry date	2025-04-18
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	4
Total items failed	6

MOT #10	2024-04-02 12:32
MOT test number	839826056722
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

MOT #9	2023-04-03 09:25
MOT test number	973051670495
Result	✓ Passed

MOT #8	2022-04-14 08:23
MOT test number	840899435860
Result	✓ Passed

MOT #7	2022-04-14 08:23
MOT test number	612053808391
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))

**MOT #6** 2021-04-19 15:13**MOT test number** 351072862107**Result** ✓ Passed**MOT #5** 2021-04-19 12:35**MOT test number** 399230975016**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2020-03-16 12:52**MOT test number** 862786149955**Result** ✓ Passed**MOT #3** 2019-03-11 14:22**MOT test number** 158654096477**Result** ✓ Passed**MOT #2** 2019-03-11 14:22**MOT test number** 845995293608**Result** ✗ Failed**Pass with rectification** Offside Rear Inner Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Rear Inner Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #1** 2018-03-16 14:35**MOT test number** 998230443765**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YK15SXH
Plate since	2015-06-29
Current registration	 YK15SXH
Plate since	2015-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-24
Last registration	2024-04-02
Complete history	See info



Registration #1	2015-03-24	19 mi
Registration #2	2018-03-16	48.159 mi
Registration #3	2019-03-11	62.261 mi
Registration #4	2019-03-11	62.261 mi
Registration #5	2020-03-16	67.383 mi
Registration #6	2020-03-16	67.383 mi
Registration #7	2020-03-16	67.383 mi
Registration #8	2020-03-16	67.383 mi
Registration #9	2020-03-16	67.383 mi
Registration #10	2020-03-16	67.383 mi
Registration #11	2020-03-16	67.383 mi
Registration #12	2020-03-16	67.383 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19HZ1607LDD