



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET II
Colour	White
Year of manufacture	2017
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-24
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #6	2024-02-15 14:51
MOT test number	785840661849
Result	✓ Passed
Next expiry date	2025-02-24
Advice	Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm both sides (5.3.4 (a) (i))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #5**

2024-02-14 14:51

**MOT test number**

500397687780

**Result**

✗ Failed

**Advice**

Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))

**Fail**

Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))

**Minor**

Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm both sides (5.3.4 (a) (i))

**Minor**

Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**Fail**

Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))

**Fail**

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #4**

2023-02-13 16:22

**MOT test number**

118713883767

**Result**

✓ Passed

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #3**

2022-02-25 13:04

**MOT test number**

840965966461

**Result**

✓ Passed



MOT #2	2021-03-16 14:02
MOT test number	158663049943
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1	2020-03-20 10:30
MOT test number	429130726075
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
24 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-27
Last registration	2024-02-15
Complete history	<a href="#">See info</a>



Registration #1	2017-03-27	17 mi
Registration #2	2020-03-20	59.965 mi
Registration #3	2021-03-16	86.829 mi
Registration #4	2022-03-20	95.277 mi
Registration #5	2023-03-20	103.725 mi
Registration #6	2024-02-15	112.173 mi
Registration #7		
Registration #8		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	6374782