





General information

Make	NISSAN
Model	LEAF TEKNA
Colour	Silver
Year of manufacture	2015
Top speed	87 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity







Internet history

Entry 1	
Date	2021-02-03
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-17
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #8	2023-05-13 09:42
MOT test number	721219278258
Result	✓ Passed
Next expiry date 2024-05-1	
Minor Front Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))	

MOT #7	2023-05-10 12:34	
MOT test number	844481340772	
Result	🗙 Failed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm, perishing (5.2	2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Arm front & rear bushes (5.3.4 (a) (i))		
Advice Nearside Rear Nail in tyre		
Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm, perishing (5.2.3	3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excess Arm front & rear bushes (5.3.4 (a) (i))	ssive movement	
Minor Front Windscreen damaged but not adversely affecting driver's view Stone chip	(3.2 (a) (i))	

МОТ #6	2022-05-11 11:09
MOT test number	455154199810
Result	✓ Passed





MOT #5	2021-05-18 13:45
MOT test number	572639788566
Result	✓ Passed
МОТ #4	2021-05-18 12:30
MOT test number	632156597923
Result	🗙 Failed

FailNearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

FailOffside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))


MOT #3		2020-06-29 08:45
MOT test	number	662357032440
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2019-07-01 10:55
MOT test number	762632425047
Result	✓ Passed
MOT #1	2018-06-28 08.50

MOT #1	2018-06-28 08:50
MOT test number	334188481505
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



GD64DLE report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-28
Last registration	2023-05-13
Complete history	See info



Registration #1	2015-01-28	28 mi
Registration #2	2018-06-28	29.392 mi
Registration #3	2019-07-01	30.551 mi
Registration #4	2020-06-29	31.342 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.300 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1525 kg
Max. allowed weight	1945 kg
Additional information	
Fuel delivery	Not Applicable
Number of doors	5

Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2	page 11/11