

Ford



General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Purple
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I







Internet history

Entry 1

Date Pictures 2022-02-03

11

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-24
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	15
Total items failed	3

MOT #17		2023-06-14 11:27
MOT test	number	725192609247
Result		🗸 Passed
Next expiry date 2024-06-24		2024-06-24
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds (5.2.3 (d) (i))

MOT #16		2022-06-23 14:34
MOT test	number	782814843388
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #15		2022-06-15 15:21
MOT test	number	283116035555
Result		🗙 Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #14	2021-06-09 10:32
MOT test number	857085263640
Result	✓ Passed
AdviceNearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))AdviceNearside Front Tyre has a cut but not deep enough to reach the ply or of up with weight of vehicle (5.2.3 (d) (i))	cords inner sidewall opens

MOT #13	2020-06-25 11:42
MOT test number	370121057617
Result	✓ Passed
MOT #12	2019-11-11 10:42
MOT test number	589811914264
Result	✓ Passed
MOT #11	2018-11-05 16:38
MOT test number	810627589459

Result

🗸 Passed



maosLNF report date: 2024-03-28

MOT #10		2018-11-05 12:34
MOT test	number	646854206504
Result		🗙 Failed
MAJOR	Offside Rear fog lamp not working (4.5.1 (a) (ii))	
MAJOR (5.2.3 (d) (Nearside Rear Tyre has a cut in excess of the requirements deep enoug i))	gh to reach the ply or cords
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #9	2017-11-24 10:09
MOT test number	370516450249
Result	✓ Passed

MOT #8	2016-11-11 13:05
MOT test number	580922179221
Result	✓ Passed

MOT #7	2016-11-11 10:01
MOT test number	172619522742
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
FailCentral Stop lamp not working (1.2.1b)	
Fail Nearside Stop lamp not working (1.2.1b)	

МОТ #6	2015-11-27 10:18
MOT test number	391354444793
Result	✓ Passed





MOT #5	2014-09-23 14:57
MOT test number	167586064232
Result	✓ Passed
MOT #4	2013-12-09 12:09
MOT test number	339493643305
Result	✓ Passed
MOT #3	2012-12-12 14:19
MOT test number	538287742369
Result	✓ Passed
MOT #2	2012-01-03 12:55
MOT test number	488493902003
Result	✓ Passed
MOT #1	2011-02-10 10:24
MOT test number	197561541472
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 24 June 2024
Tax status	Valid until 1 January
Days left	248
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



MAO8LNF report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-23
Last registration	2023-06-14
Complete history	See info



Registration #1	2008-05-23	29 mi
Registration #2	2011-02-10	6.148 mi
Registration #3	2012-01-03	8.798 mi
Registration #4	2012-12-12	13.634 mi
Registration #5	2013-12-09	19.319 mi
Registration #6	2014-09-23	24.761 mi
Registration #7	2015-11-27	33.651 mi
Registration #8	2016-11-11	39.900 mi
Registration #9	2016-11-11	39.900 mi
Registration #10	2017-11-24	46.629 mi
Registration #10 Registration #11	2017-11-24	46.629 mi
-		46.629 mi
Registration #11		46.629 mi
Registration #11 Registration #12		46.629 mi
Registration #11 Registration #12 Registration #13		46.629 mi
Registration #11 Registration #12 Registration #13 Registration #14		46.629 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		46.629 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		46.629 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	8L44829