



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT PLUS
Colour	Yellow
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 2.000 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	47 %
MOT passed	9
Failed MOT tests	10
Total advice items	31
Total items failed	6

MOT #19	2023-07-06 11:10
MOT test number	295135761876
Result	✓ Passed
Next expiry date	2024-07-05

MOT #18	2023-07-06 11:10
MOT test number	124207712983
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #17	2022-06-21 08:46
MOT test number	393402920295
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #16

2022-06-17 06:29

MOT test number

115760121136

Result

✗ Failed

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Front Undertray insecure (8.1.1 (b) (i))

MOT #15

2021-03-24 13:23

MOT test number

874185126741

Result

✓ Passed

MOT #14

2021-03-23 14:18

MOT test number

120282411944

Result

✗ Failed

MAJOR Rear Brake disc significantly and obviously worn both rear discs excessive;y corroded on inner face (1.1.14 (a) (i))**Pass with rectification** Offside Headlamp aim too high and too far to the left. (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

MOT #13

2020-12-05 09:38

MOT test number

378807247521

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-08-13 09:36**MOT test number** 777136839515**Result** ✓ Passed**MOT #11** 2020-08-12 14:26**MOT test number** 283400298507**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tread at 2mm (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2019-08-16 09:57**MOT test number** 945993574560**Result** ✓ Passed**MOT #9** 2019-08-15 09:42**MOT test number** 823388201256**Result** ✗ Failed**MAJOR** Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**MAJOR** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #8** 2018-08-03 11:13**MOT test number** 773442625549**Result** ✓ Passed

**MOT #7** 2018-07-24 12:27**MOT test number** 930397513963**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Central Rear Exhaust system insecure (6.1.2 (a))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #6** 2017-07-26 10:20**MOT test number** 409961118483**Result** ✓ Passed**MOT #5** 2017-07-25 07:56**MOT test number** 547954525705**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #4** 2016-08-23 14:30**MOT test number** 977677319176**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2016-08-23 08:23
MOT test number	158218035498
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front coil spring broken (2.4.C.1a)

MOT #2	2015-08-24 12:32
MOT test number	817746186004
Result	✓ Passed

MOT #1	2015-08-24 09:07
MOT test number	606749439257
Result	✗ Failed
Fail	Exhaust system not adequately supported front and centre brackets broken (7.1.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
5 July 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2012-11-07
Last registration	2023-07-06
Complete history	See info



Registration #1	2012-11-07	21 mi
Registration #2	2015-08-24	27.566 mi
Registration #3	2015-08-24	27.566 mi
Registration #4	2016-08-23	37.189 mi
Registration #5	2016-08-23	37.189 mi
Registration #6	2017-07-25	45.901 mi
Registration #7	2017-07-26	45.901 mi
Registration #8	2018-07-24	48.244 mi
Registration #9	2018-08-03	48.249 mi
Registration #10	2019-08-15	50.381 mi
Registration #11	2019-08-16	50.381 mi
Registration #12	2019-08-16	50.381 mi
Registration #13	2019-08-16	50.381 mi
Registration #14	2019-08-16	50.381 mi
Registration #15	2019-08-16	50.381 mi
Registration #16	2019-08-16	50.381 mi
Registration #17	2019-08-16	50.381 mi
Registration #18	2019-08-16	50.381 mi
Registration #19	2019-08-16	50.381 mi
Registration #20	2019-08-16	50.381 mi
Registration #21	2019-08-16	50.381 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEF3046313