





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V8 R
Colour	Silver
Year of manufacture	2002
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	553 Nm at 3.500 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.3 mpg
Consumption extra urban	30.7 mpg
Consumption combined	22.6 mpg
CO2 emission	314 g/km
CO2 label	M



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-02

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT hist	orv
----------	-----

MOT expiry date	2024-07-15
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #23	2023-07-01 12:15
MOT test number	960850991942
Result	✓ Passed
Next expiry date	2024-07-15

MOT #22	2022-07-15 15:38
MOT test number	483003986830
Result	✓ Passed

MOT #21	2021-07-16 14:41
MOT test number	431801182277
Result	✓ Passed

MOT #20	2019-11-22 10:37
MOT test number	632587819506
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Upper ball joint rubber gaiter slightly deteriorated

Advice Offside Rear Lower hub pin/bush joint rubber gaiter slightly deteriorated

Advice Slight oil leak at front of engine

Advice Nearside Rear Lower hub pin/bush joint rubber gaiter slightly deteriorated

MOT #18

MOT test number

757932923852

Result

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Rear Upper Brake hose has slight corrosion to ferrules n/s and o/s (3.6.B.4e)

Advice

Front Oil leak

MOT test number

Result

Advice Front Oil leak

Pass with rectification Headlamp aim too low n/s and o/s (1.8)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear Upper Brake hose has slight corrosion to ferrules n/s and o/s (3.6.8.4e)

 MOT #16
 2016-11-11 14:35

 MOT test number
 581970122100

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #15 2016-11-11 12:01

MOT test number 300591258814

Result X Failed

Fail Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

MOT #14 2015-11-20 14:08

MOT test number 170252497649

Result ✓ Passed

MOT #13 2015-11-19 10:43

MOT test number 446484783374

Result X Failed

Fail Nearside Headlamp aim too low (1.8)

Fail Nearside Rear Inner Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Offside Headlamp aim too low (1.8)

Fail Offside Rear Inner Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

MOT #12 2014-12-23 12:13

MOT test number 758077454308

Result ✓ Passed

MOT #11 2014-01-13 15:17

MOT test number 738723714026

MOT #10 2013-05-28 12:28

MOT test number 769518043104

Result

✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #9

MOT test number

Parking brake: efficiency below requirements (3.7.D.4)

2013-05-28 10:03

P15708743141

X Failed

MOT #8 2012-05-14 11:37 **MOT** test number 218805832171 Result ✓ Passed **MOT #7** 2011-06-09 09:41 **MOT** test number 886080061193 Result ✓ Passed **Advice** Offside Front Brake pad(s) wearing thin (3.5.1g) Notice Corrosion to front discs inner face Advice Offside Rear Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5	2009-06-10 16:59
MOT test number	213221969166
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #4	2008-06-03 17:00
MOT test number	670315558110
Result	✓ Passed
MOT #3	2007-06-06 18:06
MOT test number	490017257182
Result	✓ Passed
MOT #2	2006-06-07 10:30
MOT test number	884218156175
Result	✓ Passed
MOT #1	2005-06-02 17:28
MOT test number	622633955191
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-06-07
Last registration	2023-07-01
Complete history	See info



Registration #1	2002-06-07	9 mi
Registration #2	2005-06-02	13.936 mi
Registration #3	2006-06-07	15.101 mi
Registration #4	2007-06-06	17.218 mi
Registration #5	2008-06-03	19.654 mi
Registration #6	2009-06-10	23.144 mi
Registration #7	2010-05-28	23.731 mi
Registration #8	2011-06-09	30.556 mi
Registration #9	2012-05-14	34.144 mi
Registration #10	2013-05-28	38.614 mi
Registration #11	2013-05-28	38.615 mi
Registration #12	2014-01-13	41.279 mi
Registration #13	2014-12-23	42.436 mi
Registration #14		11.777 es
Registration #15		D.777 es
Registration #16		11.777 es
Registration #17		D.777 es
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #24 Registration #25		11.777 au



SRO2NVS
report date: 2024-03-28

Safety ratings

NCAP rating	
-------------	--

Video <u>see crash video</u>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1800 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	1B0203010738

CarCheck.co.uk page 13/13