



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER TD
Colour	Silver
Year of manufacture	2003
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	430 Nm at 1.400 rpm
Engine capacity	4.164 cc
Cylinders	6
Fuel type	Diesel
Consumption city	20.2 mpg
Consumption extra urban	30.4 mpg
Consumption combined	25.5 mpg
CO2 emission	340 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-02-27
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-26
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-26
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	55
Total items failed	9

MOT #24	2021-09-22 06:47
MOT test number	271934981347
Result	✓ Passed
Next expiry date	2022-09-26

MOT #23	2021-09-16 11:54
MOT test number	508857340163
Result	✗ Failed
MAJOR	Offside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
MAJOR	Horn not working (7.7 (a))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #22	2020-09-07 14:58
MOT test number	939853711895
Result	✓ Passed

MOT #21	2019-09-27 10:27
MOT test number	979821591809
Result	✓ Passed

**MOT #20** 2019-09-25 14:17**MOT test number** 100342491345**Result** ✗ Failed**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Rear Exhaust has a major leak of exhaust gases silencer split (6.1.2 (a))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**MOT #19** 2018-09-27 15:28**MOT test number** 863709612789**Result** ✓ Passed**MOT #18** 2018-09-27 14:13**MOT test number** 692437459506**Result** ✗ Failed**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #17**

2017-11-22 10:15

MOT test number

483962960540

Result

✓ Passed

Advice Nearside Front Oil leak**Advice** Rear most row of seats not fitted**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Vehicle structure has slight corrosion (6.1.B.2)**MOT #16**

2017-11-21 12:08

MOT test number

992045125771

Result

✗ Failed

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Vehicle structure has slight corrosion (6.1.B.2)**Fail** Nearside Rear Anti-roll bar attachment bracket/mounting corroded and its strength is seriously reduced (2.4.G.1)**Advice** Nearside Front Oil leak**Advice** Rear most row of seats not fitted**MOT #15**

2016-11-17 10:10

MOT test number

437691605856

Result

✓ Passed

MOT #14

2016-11-14 17:27

MOT test number

629681438579

Result

✗ Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #13	2015-11-06 13:30
MOT test number	444962385302
Result	✓ Passed
Advice	Vehicle structure has slight corrosion (6.1.A.1)

MOT #12	2014-11-10 14:42
MOT test number	719894014306
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Front Suspension arm has slight play in a pin/bearing (2.4.G.2)
Advice	Nearside Front Steering rack gaiter deteriorated (2.2.D.2d)
Advice	Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #11	2013-11-08 09:43
MOT test number	677262013356
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Passenger seat(s) missing at time of test
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Vehicle structure has slight corrosion (6.1.A.1)

**MOT #10** 2012-11-09 09:36**MOT test number** 687014512385**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #9** 2011-11-09 08:21**MOT test number** 999473611308**Result** ✓ Passed**Advice** Vehicle structure has slight corrosion (6.1.A.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Advise rear most row of seats removed**MOT #8** 2011-11-08 11:52**MOT test number** 229632111375**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Advise rear most row of seats removed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside rear brake binding (3.7.B.1)**Fail** Offside Rear Brake pivot has restricted free movement (3.5.1k)**Advice** Vehicle structure has slight corrosion (6.1.A.1)

**MOT #7** 2010-11-01 12:40**MOT test number** 443305400340**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #6** 2009-11-06 15:22**MOT test number** 100010019390**Result** ✓ Passed**Advice** Offside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #5** 2009-11-05 11:52**MOT test number** 440389409360**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Advice** Offside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Rear Brake lever has restricted free movement (3.5.1k)**Advice** Nearside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #4** 2008-11-05 16:39**MOT test number** 864730118318**Result** ✓ Passed



MOT #3	2007-10-23 10:31
MOT test number	731566997238
Result	✓ Passed
Advice	Front brake disc slightly scored (3.5.1h)
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2	2006-10-20 16:10
MOT test number	390863796492
Result	✓ Passed

MOT #1	2006-02-28 13:00
MOT test number	410089156031
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 July 2022

✕
MOT

Expired:
26 September 2022

Tax status	Expired at 31 July 2022
Days left	638 days too late
MOT expiry date	26 September 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-03-01
Last registration	2021-09-22
Complete history	See info



Registration #1	2003-03-01	28 mi
Registration #2	2006-02-28	46.146 mi
Registration #3	2006-10-20	53.014 mi
Registration #4	2007-10-23	58.099 mi
Registration #5	2008-11-05	65.562 mi
Registration #6	2009-11-05	73.564 mi
Registration #7	2009-11-06	73.566 mi
Registration #8	2010-11-01	82.462 mi
Registration #9	2011-11-08	87.987 mi
Registration #10	2011-11-09	87.990 mi
Registration #11	2012-11-09	93.157 mi
Registration #12	2013-11-08	95.051 mi
Registration #13	2014-11-10	99.744 mi
Registration #14	2015-11-06	103.857 mi
Registration #15	2016-11-06	103.857 mi
Registration #16	2017-11-06	103.857 mi
Registration #17	2018-11-06	103.857 mi
Registration #18	2019-11-06	103.857 mi
Registration #19	2020-11-06	103.857 mi
Registration #20	2021-11-06	103.857 mi
Registration #21	2022-11-06	103.857 mi
Registration #22	2023-11-06	103.857 mi
Registration #23	2024-11-06	103.857 mi
Registration #24	2025-11-06	103.857 mi
Registration #25	2026-11-06	103.857 mi
Registration #26	2027-11-06	103.857 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1940 mm
Height	1850 mm
Length	4890 mm
Wheel base	2850 mm
Kerb weight	2495 kg

Additional information

Fuel tank capacity	96 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	NOT KNOWN