



AX6IAYO

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH TDI
Colour	Silver
Year of manufacture	2012
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-05-20
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	6

MOT #12	2024-02-28 17:29
MOT test number	979477497610
Result	✓ Passed
Next expiry date	2025-03-07

MOT #11	2023-03-03 14:18
MOT test number	387442909479
Result	✓ Passed

MOT #10	2022-03-08 10:46
MOT test number	327492226153
Result	✓ Passed

MOT #9	2021-02-03 10:12
MOT test number	384894322290
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2020-02-12 09:47**MOT test number** 194430006762**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2019-02-17 22:39**MOT test number** 223811792209**Result** ✓ Passed**MOT #6** 2019-02-17 22:39**MOT test number** 895601588714**Result** ✗ Failed**Pass with rectification** Nearside Front Outer Brake disc contaminated (1.1.14 (b))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #5** 2018-01-16 14:42**MOT test number** 216723501302**Result** ✓ Passed**MOT #4** 2017-01-19 16:28**MOT test number** 235944881332**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #3**

2017-01-19 16:28

MOT test number

710198179173

Result

✗ Failed

Pass with rectification

Offside Front Headlamp not working on dipped beam (1.7.5a)

Pass with rectification

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Pass with rectification

Nearside Front Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Pass with rectification

Nearside Front Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

MOT #2

2016-01-18 15:14

MOT test number

356732787983

Result

✓ Passed

Advice

Hand brake travel long

Advice

Nearside Rear Outer Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice

Offside Rear Outer Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #1

2015-01-19 11:53

MOT test number

905349215015

Result

✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Front wipers split but clearing screen

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AX61AYO
Plate since	2024-03-29
Current registration	 AX61AYO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-02-14
Last registration	2024-02-28
Complete history	See info



Registration #1	2012-02-14	16 mi
Registration #2	2015-01-19	16.411 mi
Registration #3	2016-01-18	20.899 mi
Registration #4	2017-01-19	25.267 mi
Registration #5	2017-01-19	25.267 mi
Registration #6	2018-01-16	30.116 mi
Registration #7	2019-02-17	33.523 mi
Registration #8	2020-05-20	35.277 mi
Registration #9	2021-05-20	35.277 mi
Registration #10	2022-05-20	35.277 mi
Registration #11	2023-05-20	35.277 mi
Registration #12	2024-05-20	35.277 mi
Registration #13	2025-05-20	35.277 mi
Registration #14	2026-05-20	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2575 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CFWA293647