





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 VERVE
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

2023-01-18 11:46

✓ Passed

MOT histo

MOT #13

Result

MOT expiry date	2025-02-01
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	25
Total items failed	3

MOT #14	2024-01-10 14:01
MOT test number	509712505578
Result	✓ Passed
Next expiry date	2025-02-01
Advice Offside Rear Nail in tyre	

MOT test number	231074152023
Result	✓ Passed
MOT #12	2022-01-13 11:19
MOT test number	710209874961

MOT #11	2021-02-02 10:19
MOT test number	279085635184

Result

MOT #10	2020-09-26 11:22
MOT test number	539191685650
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT test number
969628220615

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8 2019-04-24 10:53 646352023263 **MOT** test number Result ✓ Passed **MOT #7** 2018-05-11 14:45 **MOT** test number 386622233360 Result ✓ Passed **Advice** Exhaust has a minor leak of exhaust gases (7.1.2) Advice **EML ON Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #6		2017-05-13 08:43
MOT test	number	440647564235
Result		✓ Passed
Advice	EML ON	
Advice	Nearside Rear BRAKE SCREAMING DURING RBT	
Advice	Offside Rear TYRE CRACKING ON OUTER SHOULDER	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	

CarCheck.co.uk page 3/12



report date: 2024-03-29

2016-05-13 09:12 **MOT #5** 582868666207 **MOT test number** ✓ Passed Result **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Rear exhaust mount broken Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Advice Front Brake pad(s) wearing thin (3.5.1g) Engine man light on Advice **Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #4		2015-05-18 16:25
MOT test	number	917658135106
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3	.5.1i)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)

MOT #3	2014-09-22 14:50
MOT test number	859845464281
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice

Oil leak

MOT #1	2012-09-24 14:07
MOT test number	955888962282
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

e when motory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-22
Last registration	2024-01-10
Complete history	See info



Registration #1	2009-09-22	15 mi
Registration #2	2012-09-24	22.382 mi
Registration #3	2013-09-23	31.444 mi
Registration #4	2014-09-22	40.099 mi
Registration #5	2015-05-18	45.352 mi
Registration #6	2016-05-13	47.520 mi
Registration #7	2017-05-13	50.357 mi
Registration #8	2018-05-11	52.770 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1214 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number FSW86163295