



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Silver
Year of manufacture	-
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #19	2021-06-23 13:57
MOT test number	924507399967
Result	✓ Passed
Next expiry date	2022-07-15
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18	2021-06-16 12:43
MOT test number	508950474370
Result	✗ Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
MAJOR	Offside Rear Sub-frame pin or bush excessively worn axle bush (5.3.4 (a) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle bush (5.3.4 (a) (i))

MOT #17	2020-07-16 14:27
MOT test number	489875074442
Result	✓ Passed
Advice	Steering rack noisy
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil light on intermittent

**MOT #16** 2020-07-16 09:48**MOT test number** 891795315422**Result** ✗ Failed**MAJOR** Driver's airbag obviously inoperative (7.1.5 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Steering rack noisy**Advice** Oil light on intermittent**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2019-06-27 14:09**MOT test number** 161538872962**Result** ✓ Passed**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2019-06-27 08:11**MOT test number** 508336298497**Result** ✗ Failed**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2018-07-12 10:32**MOT test number** 648746837924**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Travel park brake**MOT #12** 2017-10-20 19:04**MOT test number** 114444103963**Result** ✓ Passed**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11** 2017-10-20 15:47**MOT test number** 627895452549**Result** ✗ Failed**Fail** Central Exhaust system not adequately supported centre part (7.1.1)**Advice** Nearside Front Suspension arm synthetic mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Emission cannot be tested due to excessive blue smoke**Fail** Exhaust emits excessive dense blue smoke during acceleration (7.3.A.2c)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #10** 2016-10-12 14:23**MOT test number** 959144499545**Result** ✓ Passed**Advice** Offside Front tyre worn

**MOT #9** 2016-10-12 10:37**MOT test number** 906669715274**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front tyre worn**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2015-09-29 09:40**MOT test number** 290644677854**Result** ✓ Passed**MOT #7** 2014-09-18 14:51**MOT test number** 755901564217**Result** ✓ Passed**Notice** The spare tyre is also below 1.6mm**MOT #6** 2014-09-18 11:25**MOT test number** 546381364222**Result** ✗ Failed**Notice** The spare tyre is also below 1.6mm**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #5** 2013-09-27 15:42**MOT test number** 277530073246**Result** ✓ Passed

**MOT #4** 2012-09-19 15:59**MOT test number** 818463962245**Result** ✓ Passed**MOT #3** 2012-09-19 11:20**MOT test number** 428783862224**Result** ✗ Failed

- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #2 2011-09-19 10:10**MOT test number** 167802561295**Result** ✓ Passed**MOT #1** 2010-09-17 10:26**MOT test number** 884530160210**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	KT07AWO
Plate since	2019-06-29
Current registration	KT07AWO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-08-28
Last registration	2021-06-23
Complete history	See info



Registration #1	2007-08-28	17 mi
Registration #2	2010-09-17	30.122 mi
Registration #3	2011-09-19	37.769 mi
Registration #4	2012-09-19	46.255 mi
Registration #5	2012-09-19	46.261 mi
Registration #6	2013-09-27	55.793 mi
Registration #7	2014-09-18	64.785 mi
Registration #8	2014-09-18	64.786 mi
Registration #9	2015-09-29	72.671 mi
Registration #10	2016-10-12	80.897 mi
Registration #11	2016-10-12	80.897 mi
Registration #12	2016-10-12	80.897 mi
Registration #13	2016-10-12	80.897 mi
Registration #14	2016-10-12	80.897 mi
Registration #15	2016-10-12	80.897 mi
Registration #16	2016-10-12	80.897 mi
Registration #17	2016-10-12	80.897 mi
Registration #18	2016-10-12	80.897 mi
Registration #19	2016-10-12	80.897 mi
Registration #20	2016-10-12	80.897 mi
Registration #21	2016-10-12	80.897 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531