



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE R-DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-12-23
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-11
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	58
Total items failed	7

MOT #19	2024-01-08 11:56
MOT test number	394041868917
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Offside Rear tyre feathering inner edge
Advice	Nearside Front Tyre worn close to legal limit/worn on edge close to limit. 205/50/17 (5.2.3 (e))
Advice	Suspect chuffing injector- no fumes in cab
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge lightly wearing inner edge (5.2.3 (e))

MOT #18	2023-01-12 14:55
MOT test number	318753389609
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)

**MOT #17** 2023-01-06 14:24**MOT test number** 903764461875**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #16** 2022-01-12 16:45**MOT test number** 407183176036**Result** ✓ Passed**MOT #15** 2022-01-10 15:41**MOT test number** 717637043190**Result** ✗ Failed**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Rear heatshield loose**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14** 2021-05-18 14:03**MOT test number** 539002289187**Result** ✓ Passed**Advice** Oil leak from engine but not excessive**MOT #13** 2020-05-18 09:39**MOT test number** 527808024637**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2020-05-14 14:49

**MOT test number**

886732005377

**Result****✗ Failed**

- MAJOR** Nearside Rear Anti-roll bar linkage insecurely attached bolt snapped (5.3.3 (a) (i))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn bottom arm bush (5.3.4 (a) (i))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn bottom arm bush (5.3.4 (a) (i))
- MAJOR** Electronic braking system warning device indicates a fault anti skid warning (1.7 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2019-04-12 12:10

**MOT test number**

379387290707

**Result****✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2018-04-19 15:36

**MOT test number**

751618476337

**Result****✓ Passed**

**MOT #9** 2018-04-16 07:02**MOT test number** 168005564371**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Bonnet cannot be secured in the closed position (8.4.1)**MOT #8** 2017-07-25 07:21**MOT test number** 671394455765**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear tyre worn on inner edge**MOT #7** 2017-07-24 09:14**MOT test number** 614675054864**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear tyre worn on inner edge**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #6	2016-07-27 13:55
MOT test number	659870697016
Result	✓ Passed
Advice	Rear brake pads low

MOT #5	2015-07-21 13:59
MOT test number	388792505496
Result	✓ Passed
Notice	N/s/f tyre worn close to legal limit

MOT #4	2014-07-29 14:32
MOT test number	567110314299
Result	✓ Passed
Advice	Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	Osf outer position bulb inop
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Front front brake fluctuating, but not excessively (3.7.B.3)
Advice	Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Nail in offside front tyre
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Under-trays fitted obscuring some underside components

**MOT #3**

2014-07-29 10:32

**MOT test number**

937400314283

**Result****✗ Failed**

**Advice** Offside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Under-trays fitted obscuring some underside components

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Osf outer position bulb inop

**Advice** Front front brake fluctuating, but not excessively (3.7.B.3)

**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Nearside Rear Lower Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Nail in offside front tyre

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**Advice** Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #2**

2013-07-29 11:46

**MOT test number**

658840013287

**Result****✓ Passed****MOT #1**

2012-06-26 16:05

**MOT test number**

666168472152

**Result****✓ Passed**

**Notice** Child seat fitted not allowing full inspection of adult belt





Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
11 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	11 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-07-15
Last registration	2024-01-08
Complete history	<a href="#">See info</a>



Registration #1	2009-07-15	23 mi
Registration #2	2012-06-26	84.164 mi
Registration #3	2013-07-29	93.161 mi
Registration #4	2014-07-29	99.570 mi
Registration #5	2014-07-29	99.572 mi
Registration #6	2015-07-21	104.016 mi
Registration #7	2016-07-27	107.894 mi
Registration #8	2017-07-24	111.973 mi
Registration #9	2017-07-25	111.973 mi
Registration #10	2018-04-16	114.020 mi
Registration #11	2018-04-19	114.020 mi
Registration #12	2019-05-20	115.577 mi
Registration #13	2019-05-20	115.577 mi
Registration #14	2019-05-20	115.577 mi
Registration #15	2019-05-20	115.577 mi
Registration #16	2019-05-20	115.577 mi
Registration #17	2019-05-20	115.577 mi
Registration #18	2019-05-20	115.577 mi
Registration #19	2019-05-20	115.577 mi
Registration #20	2019-05-20	115.577 mi
Registration #21	2019-05-20	115.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	704037