



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY CC
Colour	Silver
Year of manufacture	2012
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	125 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-05-29
Pictures	51
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	10

MOT #13	2023-05-19 10:06
MOT test number	459786049378
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

MOT #12	2023-05-19 10:06
MOT test number	127465604865
Result	✗ Failed
Advice	Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

MOT #11	2022-06-06 14:36
MOT test number	831136659341
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 245/45/17 (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 245/45/17 (5.2.3 (e))

**MOT #10** 2021-06-03 13:01**MOT test number** 897571096774**Result** ✓ Passed**MOT #9** 2020-07-28 11:57**MOT test number** 265063877323**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Undertrays fitted obscuring underside components**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2019-10-14 14:17**MOT test number** 751555190817**Result** ✓ Passed**MOT #7** 2019-10-12 13:46**MOT test number** 471549300823**Result** ✗ Failed**Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #6** 2019-08-19 12:57**MOT test number** 479577503896**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))
- Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))

MOT #5 2018-11-29 16:54**MOT test number** 656206476866**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin and offside front (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and offside front (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge and offside front (5.2.3 (e))

MOT #4 2017-11-18 09:33**MOT test number** 335228889433**Result** ✓ Passed

- Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended Rear Bush (2.4.F.3)
- Advice** Exhaust has a minor leak of exhaust gases DPF Gasket (7.1.2)

**MOT #3** 2017-11-16 12:21**MOT test number** 928817476183**Result** ✗ Failed**Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended Rear Bush (2.4.F.3)**Fail** Front Headlamp cleaning device inoperative (1.7.2)**Advice** Exhaust has a minor leak of exhaust gases DPF Gasket (7.1.2)**MOT #2** 2016-08-15 12:19**MOT test number** 762090089498**Result** ✓ Passed**MOT #1** 2015-12-02 15:55**MOT test number** 701789981800**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
5 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-19
Last registration	2023-05-19
Complete history	See info



Registration #1	2012-12-19	8 mi
Registration #2	2015-12-02	32.452 mi
Registration #3	2016-08-15	36.715 mi
Registration #4	2017-11-16	46.369 mi
Registration #5	2017-11-18	46.370 mi
Registration #6	2018-11-29	63.186 mi
Registration #7	2019-08-19	64.037 mi
Registration #8	2019-10-12	64.053 mi
Registration #9	2019-10-12	64.053 mi
Registration #10	2019-10-12	64.053 mi
Registration #11	2019-10-12	64.053 mi
Registration #12	2019-10-12	64.053 mi
Registration #13	2019-10-12	64.053 mi
Registration #14	2019-10-12	64.053 mi
Registration #15	2019-10-12	64.053 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1550 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

CFFB987791