



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLA CLA220 CDI AMG SPORT
Colour	Silver
Year of manufacture	2013
Top speed	143 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	125 kW / 170 HP / 175 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-06-23
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-22
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-25
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	28
Total items failed	6

MOT #112023-08-26 12:50

MOT test number689465350307

Result✓ Passed

Next expiry date2024-08-25

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside front tyre worn smooth on inner & outer edges
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2023-08-25 15:19

**MOT test number**

874701863125

**Result**

✗ Failed

- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside front tyre worn smooth on inner & outer edges
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9**

2022-06-08 13:53

**MOT test number**

774011736491

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged lumpy (5.2.3 (d) (ii))
- Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing lumpy (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2021-06-23 16:02

**MOT test number**

263212724654

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2020-11-20 11:44**MOT test number** 720548010599**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2019-11-27 16:16**MOT test number** 131429771801**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2019-11-20 15:53**MOT test number** 361009446300**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #4** 2018-11-23 16:12**MOT test number** 934572605047**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-11-23 10:53**MOT test number** 100076918772**Result** ✗ Failed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #2	2017-10-18 10:23
MOT test number	800403410921
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Both rear tyres wearing on inner edges
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-09-12 11:39
MOT test number	459846018344
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Both rear tyres stepped on inside



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
25 August 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	25 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>KV63KXD</b>
Plate since	2019-03-29
Current registration	 <b>KV63KXD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-13
Last registration	2023-08-26
Complete history	<a href="#">See info</a>



Registration #1	2013-09-13	24 mi
Registration #2	2016-09-12	51.907 mi
Registration #3	2017-10-18	60.904 mi
Registration #4	2018-11-23	75.899 mi
Registration #5	2018-11-23	75.899 mi
Registration #6	2019-11-20	91.838 mi
Registration #7	2019-11-27	91.883 mi
Registration #8	2019-11-27	91.883 mi
Registration #9	2019-11-27	91.883 mi
Registration #10	2019-11-27	91.883 mi
Registration #11	2019-11-27	91.883 mi
Registration #12	2019-11-27	91.883 mi
Registration #13	2019-11-27	91.883 mi
Registration #14	2019-11-27	91.883 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2032 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1425 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4

---

**Number of axles**

2

**Engine number**

65193031639559

---