





report date: 2024-03-29

General information

Make	BMW
Model	Z3 Z3 ROADSTER
Colour	Silver
Year of manufacture	2001
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	117 BHP
Max. torque	180 Nm at 3.900 rpm
Engine capacity	1.895 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	47.9 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2022-12-15
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	22
Total items failed	22

MOT #18	2021-12-16 16:49
MOT test number	496411791525
Result	✓ Passed
Next expiry date	2022-12-15

MOT #	17	2021-12-08 16:34
MOT te	st number	239097427098
Result		X Failed
Fail	Offside Front Side repeater not working (4.4.1 (a) (ii))	
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamp	ps (4.7.1 (b) (ii))
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Offside Seat belt retracting mechanism defective (7.1.2 (e))	

MOT #16	2020-09-16 15:00
MOT test number	861399688644
Result	✓ Passed

MOT #15	2019-09-19 15:23
MOT test number	303748179428
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14		2018-08-25 11:50
MOT test i	number	431183782742
Result		✓ Passed
MOT #13		2017-09-06 11:36
MOT test i	number	666986350151
Result		✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Front coil spring corroded (2.4.C.1b)	
Advice	Offside Outer Body has slight corrosion sill (6.1.B.2)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Outer Body has slight corrosion sill (6.1.B.2)	

MOT #12		2016-08-25 11:28
MOT test	number	922027060873
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #11		2015-09-02 21:02
MOT test	number	478301972203
Result		✓ Passed
Advice	Brake pipe slightly corroded both front to rear (3.6.B.2c)	
Advice	Brake pipe slightly corroded both rear (3.6.B.2c)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10		2014-08-12 12:29
MOT test	number	306274024213
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Front Steering system lightly rubbing (2.2.D.2a)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Play in steering rack inner joint(s)	
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front Side repeater slightly discoloured (1.4.A.2f)	
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #9	2013-08-15 09:53
MOT test number	349657423469
Result	✓ Passed
Advice Brake pipe slightly corroded (3.6.B.2c)	

MOT #8	2012-08-13 11:15
MOT test number	649096622213
Result	✓ Passed
MOT #7	2011-09-12 16:10
MOT test number	975635351277
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #6

MOT test number

829743051263

Result

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #5 2011-08-01 10:22 **MOT** test number 505433211257 Result **X** Failed Fail Offside Rear Stop lamp not working (1.2.1b) Fail Rear coil spring incomplete (2.4.C.1a) Fail Offside Front Brake pipe excessively corroded (3.6.B.2c) **Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c) Fail Offside Front Front position lamp(s) not working (1.1.A.3b) Fail Offside Rear Rear position lamp(s) not working (1.1.A.3b) Fail Nearside Front Mechanical brake component has restricted free movement (3.5.1k) Fail Brakes imbalanced across an axle (3.7.B.5b) Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #4	2008-04-11 10:09
MOT test number	644722008184
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #3 2008-04-08 12:10 **MOT test number** 901899298076 Result × Failed Fail Nearside Front Front position lamp(s) not working (1.1.A.3b) Rear Stop lamp not working (1.2.1b) Fail Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3) Fail Offside Rear Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d) Fail Front Ball joint has excessive play (2.2.B.1f) Exhaust system not adequately supported (7.1.1) Fail

MOT #2		2006-10-06 12:41
MOT test number		962859376263
Result		✓ Passed
MOT #1		2006-10-06 12:41
MOT test number		921929876289
Result		X Failed
Pass with rectification	Offside Front Side repeater incorrect colour (1.4.A.2f)	
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)	

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2001-09-12
Last registration	2021-12-16
Complete history	See info



Registration #1	2001-09-12	12 mi
Registration #2	2006-10-06	59.557 mi
Registration #3	2008-04-08	74.681 mi
Registration #4	2008-04-11	74.681 mi
Registration #5	2011-08-01	82.263 mi
Registration #6	2011-09-10	82.264 mi
Registration #7	2011-09-12	82.264 mi
Registration #8	2012-08-13	82.724 mi
Registration #9	2013-08-15	82.870 mi
Registration #10	2014-08-12	86.700 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.00 44
Registration #19		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	1692 mm
Height	1288 mm
Length	4025 mm
Wheel base	2446 mm
Kerb weight	1220 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	04649802

CarCheck.co.uk page 13/13